Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ሳ ሮክ	Artesla
いしい	MI LCSIG

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Ехрие
5.	Lease Serial No.

SUNDRY Do not use thi abandoned wel	NMNM7	NMNM70309 6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NMNM84596			
Type of Well Gas Well	er			8. Well Name and No. CENTURY PLANT 1			
2. Name of Operator YATES PETROLEUM CORPO	Contact: DRATIONE-Mail: laura@yate	LAURA WATTS espetroleum.com		9. API Well No. 30-015-26419-00-S1			
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	T	3b. Phone No. (include area code Ph: 575-748-4272 Fx: 575-748-4585		10. Field and Pool, or Exploratory N DAGGER DRAW			
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)	11. County	11. County or Parish, and State			
Sec 34 T19S R24E SESE 660FSL 660FEL				EDDY COUNTY, NM			
12. CHECK APPR	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR	OTHER DATA			
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Re	sume)			
	☐ Alter Casing	□ Fracture Treat	☐ Reclamation	■ Well Integrity			
☐ Subsequent Report	Casing Repair	■ New Construction	■ Recomplete	☐ Other			
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	☐ Temporarily Abando	on			
_	Convert to Injection	Plug Back	■ Water Disposal				
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab- determined that the site is ready for fi Yates Petroleum Corporation	ally or recomplete horizontally, k will be performed or provide operations. If the operation re bandonment Notices shall be fil nal inspection.)	give subsurface locations and measing the Bond No. on file with BLM/BL sults in a multiple completion or reced only after all requirements, included complete this well as follows:	ured and true vertical depths of A. Required subsequent reportion in a new interval, a ding reclamation, have been controlled.	f all pertinent markers and zones. ts shall be filed within 30 days Form 3160-4 shall be filed once			
1. MIRU WSU and all safety equipment necessary. ND tree and NU BOP. 2. POOH with the existing production equipment. 3. Make a gauge ring and junk basket run to 7,610 ft. Set a CIBP at 7,603 ft and cap it with 3 FE ATTACHED FOR ft cernent. 4. Set a 60 sx plug from 5,153 ft - 5,463 ft across the Wolfcamp top and DV tool. WOC and tag the plug, reset if necessary. 5. Set a 30 sx plug from 3,864 ft - 4,034 ft across the Abo top. Pressure test the casing to 3500 RECEIVED psi. 6. Pull a CBL/GR/CCL log to verify the cement top, then perforate Glorieta-Yeso 1,978 ft - 2,222 ft (73 holes).							
14. I hereby certify that the foregoing is	true and correct.			NMOCD ARTESIA			
Com	# Electronic Submission For YATES PETRO mitted to AFMSS for proce	232138 verified by the BLM We DLEUM CORPORATION, sent to ssing by JENNIFER MASON or	to the Carlsbad [*] n 02/04/2014 (14JAM00735	, , , , , , , , , , , , , , , , , , ,			
Name(Printed/Typed) LAURA W	ATTS	Title REGR	REPORTING TECHNICA	N N			
Signature (Electronic S	ubmission)	Date 01/15/2	2014 APP	RUVED			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By	itable title to those rights in the	e subject lease Office	BUZEAU OF I	AD JULD OFFICE			

itle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #232138 that would not fit on the form

32. Additional remarks, continued


7. Pump a fracture treatment (treating schedule attached) at 100 BPM down the 7 inch casing limiting the surface treating pressure to 3000 psig. Set a pop off valve at 3500 psi. 8. Flow the well back and allow the well to clean up. TIH with tubing to check for fill and to ensure that the perforations are not covered. POOH. 9. TIH with TAC and 2.875 inch tubing. Swab the well until it cleans up, then TIH with pump. Turn well to production.


Wellbore schematics attached

Treating Schedule

	1	1	T		T	T	T	
Sta.#	Fluid	Stg. Type	Cin. Vol. (gals)	Rate (bpm)	Proppant	Conc. (lb/gal)	Stage Prop. (lbs)	Cum, Prop. (lbs)
1	Slick Water	Prepad	100	20		0.0	0	0
2	20% HCL	Acid	4,000	40		0.0	0	0
3	Slick Water	Prepad	2,000	100		0.0	0	0
4	Slick Water	Pad	56,000	100		0,0	0	0
5	Slick Water	Slurry	4,500	100	100 Mesh	0.2	900	900
6	Slick Water	Sweep	4,500	100	100 Moon	0.0	0	900
7	Slick Water	Slurry	4,500	100	100 Mesh	0.3	1,350	2,250
8	Slick Water	Sweep	4,500	100	, too moon	0.0	0	2,250
9	Slick Water	Siurry	4,500	100	100 Mesh	0.4	1,800	4,050
10	Slick Water	Sweep	4,500	100		0.0	0	4,050
11	Slick Water	Slurry	4,500	100	100 Mesh	0.5	2,250	6,300
12	Slick Water	Sweep	4,500	100		0.0	0	6,300
13	Slick Water	Slurry	4,500	100	100 Mesh	0.6	2,700	9,000
14	Slick Water	Sweep	4,500	100		0.0	. 0	9,000
15	Slick Water	Slurry	4,500	100	100 Mesh	0.7	3,150	12,150
16	Slick Water	Sweep	4,500	100	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0.0	0	12,150
17	Slick Water	Slurry	4,500	100	100 Mesh	0.8	3,600	15,750
18	Slick Water	Sweep	4,500	100	700 11100.1	0.0	0,000	15,750
. 19	Slick Water	Slurry	4,500	100	100 Mesh	0.9	4,050	19,800
20	Slick Water	Sweep	4,500	100	100 11.001	0.0	0	19,800
21	Slick Water	Slurry	4,500	100	100 Mesh	1.0	4,500	24,300
22	Slick Water	Pad	10,700	100	100 311011	0.0	0	24,300
23	Slick Water	Slurry	20,000	100	40/70 Brady	0.2	4,000	28,300
24	Slick Water	Sweep	6,000	100		0.0	0	28,300
25	Slick Water	Slurry	20,000	100	40/70 Brady	0.3	6,000	34,300
26	Slick Water	Sweep	6,000	100		0.0	0	34,300
27	Slick Water	Slurry	20,000	100	40/70 Brady	0.4	8,000	42,300
28	Slick Water	Sweep	6,000	100		0.0	0	42,300
29	Slick Water	Slurry	20,000	100	40/70 Brady	0.5	10,000	52,300
30	Slick Water	Sweep	6,000	100		0.0	0	52,300
31	Slick Water	Slurry	20,000	100	40/70 Brady	0.6	12,000	64,300
32	Slick Water	Sweep	6,000	100		0.0	0	64,300
33	Slick Water	Slurry	20,000	100	40/70 Brady	0.7	14,000	78,300
34	Slick Water	Sweep	6,000	100		0.0	0	78,300
35	Slick Water	Slurry	20,000	100	40/70 Brady	0.8	16,000	94,300
36	Slick Water	Sweep	6,000	100	-	0.0	0	94,300
37	Slick Water	Slurry	23,000	100	40/70 Brady	0.9	20,700	115,000
38	Slick Water	Sweep	6,000	100		0.0	0	115,000
39	Slick Water	Slurry	24,000	100	40/70 Brady	1.0	24,000	139,000
40	Slick Water	Pad	17,000	100	·	0.0	0	139,000
41	Slick Water	Siurry	17,000	100	16/30 Brady	1.0	17,000	156,000
42	Slick Water	Slurry	24,000	100	16/30 Brady	2.0	48,000	204,000
43	Slick Water	Slurry	32,000	100	16/30 Brady	3.0	96,000	300,000
44	Slick Water	Flush	3,270	100		0.0	0	300,000
45	Slick Water	Flush	25200	100		0.0	0	300,000
	Totals						300,000	
								

Estimated Surface Treating Pressure = 2,223 psig. Maximum Surface Treating Pressure = 3,500 psig.





Century Plant 1 30-015-26419 Yates Petroleum Corporation February 28, 2014 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by May 28, 2014.

- 1. Operator shall set a balanced Class H Cement plug from 9,074'-8,884' to seal the top of the Morrow formation.
- 2. Operator shall set CIBP at 7,603' and place 25 sx Class H Cement on top. Tag required.
- 3. Operator's step 4, move plug to 5,500'-5,190' to ensure the DV tool is covered. WOC. Tag required.
- 4. Step 5 is okay.
- 5. Submit CBL to BLM.
- 6. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 7. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 8. Surface disturbance beyond the originally approved pad must have prior approval.
- 9. Closed loop system required.
- 10. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 11. Operator to have H2S monitoring equipment on location.

- 12. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 13. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 14. See attached for general requirements.

JAM 022814

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.