## BLM Carlsbad Field Office

Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Expires: July 3	
ease Serial No.	

BUREAU OF LAND MANAGEMENT			5. Lease Serial No. NMNM78213				
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an							
abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No			
1. Type of Well Gas Well St Other: UNKNOWN OTH			8. Well Name and No. WALT CANYON AMA FEDERAL 9				
2. Name of Operator Contact: LAURA WATTS YATES PETROLEUM CORPORATIONE-Mail: laura@yatespetroleum.com			9. API Well No. 30-015-32468				
105 SOUTH FOURTH STREET		3b. Phone No. (include are Ph: 575-748-4272 Fx: 575-748-4585	5-748-4272		10. Field and Pool, or Exploratory INDIAN BASIN; UP ASSOC		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State				
Sec 3 T22S R24E NWSW 1370FSL 915FWL			EDDY COUNTY COUNTY, NM				
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE NATURE	OF NOTICE, R	EPORT, OR OTHE	R DATA		
TYPE OF SUBMISSION		TY	PE OF ACTION				
□ Notice of Intent	☐ Acidize	Deepen	☐ Produc	tion (Start/Resume)	☐ Water Shut-O	ff	
- ,	☐ Alter Casing	☐ Fracture Treat	☐ Reclan	nation	■ Well Integrity	7	
Subsequent Report	Casing Repair	☐ New Constructi	on 🗖 Recom	plete	□ Other		
☐ Final Abandonment Notice	☐ Change Plans	🔀 Plug and Aband	on 🔲 Tempo	rarily Abandon			
	Convert to Injection	☐ Plug Back	☐ Water	Disposal	A Company of the comp		
1/12/14 - NU BOP. 1/13-28/14 - RIH with GR and 6,421 ft after several attempts in pulled up 30 ft. Pumped 25 at 6,421 ft, pulled up 30 ft and Tagged cement at 5,685 ft. T Circulated hole with salt gel. Displaced to 5,238 ft. Tagged Class C Neat. Displaced to 3 witness tag. Perfd at 2,890 ft. Per Pressured up to 1200 psi. Til	. Tagged collaps86 casir 0 sacks C Neal 15.2 ppg pumped 300 sacks C at ested casing to 500 psi Perfd 4 holes at 5.388 ft. I plug at 5.176 ft. BLM ok 5.127 ft. WCC. Tagged I Squeezed 50 sacks C c d at 17/40 ft. Could not of	ig at 6,421 ft. Rofated by Displaced with 10 bbls 15 lb with 3 percent CaC BLM approved to continue pumped 50 sacks Classid. Period at 3,277 ft. POC at 2,925 ft. BLM with the period by the continue period b	nut could not get if resh water. Tax 21. LCM ahead ue plug and aban s C Neat. umped 50 sacks as on location to 770 ft. WOC.	at 1/4/16/20 ged WOC. Accepted as to ple Liability under bo Surface restoration	AMATICIN 7-29-14  uzging of the well and is interpolated us completed.		
					RECEL	<u>VE</u> D	
14. I hereby certify that the foregoing is	Electronic Submission # For YATES PETRO	234698 verified by the BL DLEUM CORPORATION, or processing by DEBOR	sent to the Carisb	ad (	MAR 19	2014	
Name (Printed/Typed) LAURA W	ATTS	Title R	EG REPORTING	TECHNICIAN	NMOCD A	<u>rtesia</u>	
Signature (Electronic	Submission)	Date 02	2/06/2014PTF1	) EUB BEC	<u> </u>		
	THIS SPACE FO	R FEDERAL OR ST	ATE OFFICE U	SE			
Approved By		Title	1140	1.2 0004	Date		
Approved By  Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conditions.	nitable title to those rights in the act operations thereon.	not warrant or subject lease Office	MAR J.	nr			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any person knowing to any matter within its junisc		ake to any department o	nagency of the United	টু কু ও	
** OPER A	OR-SUBMITTED ** O	PERATOR SURMET	ED ** OPERAT	COP_SUBMITTER	\ **		

## Additional data for EC transaction #234698 that would not fit on the form

## 32. Additional remarks, continued

TOC at 1.703 ft. BLM did not approve. Re-spot 25 sacks Class C cement. WOC. Tagged TOC at 1.474 ft. BLM witnessed tag. Perfd at 150 ft. Pumped 80 sacks Class C into formation. ND BOP. Topped off well.

2/4/14 - Dug out cellar and cut off wellhead. Installed dry hole marker. Filled cellar. WELL IS PLUGGED AND ABANDONED.