

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

MAR 27 2014

NM OGD ARTESIA

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐

2. Name of Operator

ARMSTRONG ENERGY CORPORATION

3. Address of Operator

P.O. Box 1973, Roswell, NM 88022-1973

4. Well Location

Unit Letter A : 660 feet from the North line and 660 feet from the East line
Section 11 Township 10S Range 26E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

WELL API NO.

30-005-63644

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VO-5576

7. Lease Name or Unit Agreement Name

Z-28 State

8. Well Number

1

9. OGRID Number

001092

10. Pool name or Wildcat

Foor Ranch Wolfcamp

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-10-14 ND wellhead, install BOP, unseat pkr and POH.

3-11-14 RIH w/ 5-1/2" CIPB, set @ 5650', circ hole w/ Brine mud, spot 25 sx plug on top of CIBP, POH, WOC. RIH, tag @ 5417', 233' plug. POH to 4724', spot 25 sx plug, POH, WOC. RIH, tag @ 4482', 242' plug, POH. SDON

3-12-14 Work csg, cut @ 3148', POH, LD 66 jts and 2 cut-offs. RIH w/ tbg to 3198', spot 50 sx plug, POH, WOC. SDON

3-13-14 RIH, tag @ 3041', 184' plug. POH to 2411', spot 50 sx Class "C" cement w/ 2% CaCl₂, POH, WOC. TIH, tag @ 2266', 145' plug. POH to 1075', spot 50 sx plug, POH, WOC. SDON.

3-14-14 RIH, tag @ 1029', 46' fill. Spot 30 sx @ 1029', POH, WOC. RIH, tag @ 926', 149' total plug. POH to 260', spot 25 sx Class "C" cement. POH to 65', spot 20 sx Class "C" cement to Surface. Cut off wellhead, install Dry Hole plate, back-fill cellar, cut off anchors, clean location. RD and move out.

Will notify OCD when location is rehabilitated and re-seeded.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms. www.emnrd.state.nm.us/oed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Vice President - Operations

DATE

3/25/14

Type or print name

Bruce A. Stubbs

E-mail address:

bastubbs@armstrongenergycorp.com

PHONE:

575-625-2222

For State Use Only

APPROVED BY:

TITLE

Dr. H. Spewer

DATE

3/27/14

Conditions of Approval (if any):

* Submit Subsequent C-103