State of New Mexico Form C-103 Submit 1 Copy To Appropriate District Office District I Energy, Minerals and Natural Resources October 13, 2009 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District_II 30-005-63585 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE 🛛 1000 Rio Brazos Rd., Aztec, NM 87410 FEE District IV Santa Fe, NM 87505 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 V0-5577 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Overeasy State DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number **Armstrong Energy Corporation** 001092 3. Address of Operator 10. Pool name or Wildcat P.O. Box 1973, Roswell, NM 88202-1973 Foor Ranch Pre-Permian 4. Well Location feet from the NORTH line and 660 Unit Letter feet from the WEST 6 Township 10S 27E **NMPM** Chaves County Section Range 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ REMEDIAL WORK ALTERING CASING □ PLUG AND ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. \boxtimes TEMPORARILY ABANDON П P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15:7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 3-03-14 RU, ND wellhead and install BOP. Work tbg to release pkr, SI. SDON 3-04-14 Unseat pkr, POH w/ tbg and pkr. TIH w/ 5-1/2" CIBP and set @ 5720', circ hole w/ Brine mud, spot 25 sx Class "C" cement on top of CIBP, POH, WOC. RIH and tag @ 5474', 246' plug. POH to 4807', spot 25 sx plug, POH, WOC. RIH and tag @ 4575', 232' plug. Weld on lift sub, work csg, shot csg @ 3410', POH and LD 77 its and 2 cut-offs, SDON 3-06-14 RIH to 3475', spot 50 sx, POH, WOC. RIH and tag @ 3290', 185' plug. POH to 2568', spot 50 sx plug, POH. SDON RIH, tag @ 2449', 119' plug. POH to 1007', spot 50 sx plug, POH, WOC. RIH, tag @ 855', 152' plug. POH to 357', 3-08-14 spot 25 sx plug. POH to 65', spot 20 sx plug to Surface. Cut off wellhead, install Dry Hole plate, back-fill cellar, cut off anchors, clean location. RD, move out. Approved for plugging of well bore only. Liability under bond is retained pending receipt Will notify OCD when location is rehabilitated and re-seeded. of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under MAR 27 2014 Forms, www.cmnrd.state.nm.us/ocd. NAMOCD ARTESIA Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Vice President – Operations DATE 03/25/14 TITLE Type or print name _____Bruce A. Stubbs _____ E-mail address: <u>bastubbs@armstrongenergycorp.com</u> PHONE: __(575) 625-2222

For State Use Only

APPROVED BY:

Submit Subsequent C-103 Conditions of Approval (if any):