

State of New Mexico  
Energy, Minerals and Natural ResourcesForm C-103  
Revised July 18, 2013OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-61184
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ARMSTRONG ENERGY CORPORATION		6. State Oil & Gas Lease No. L-6907
3. Address of Operator P.O. Box 1973, Roswell, NM 88022-1973		7. Lease Name or Unit Agreement Name Viking State Com
4. Well Location Unit Letter C : 990 feet from the North line and 1980 feet from the West line Section 19 Township 9S Range 27E NMPM Chaves County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3809' GR		9. OGRID Number 001092
		10. Pool name or Wildcat Pecos Slope Abo

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
 DOWNHOLE COMMINGLE ☐  
 CLOSED-LOOP SYSTEM ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPNS. ☐ P AND A ☒  
 CASING/CEMENT JOB ☐

OTHER: ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-18-14 Set CIBP @ 4875', circ hole with Brine mud, spot 30 sx Class "C" cement on top of CIBP, POH, WOC. RIH, tag @ 4446', 429' plug.

3-19-14 Weld on lift sub, work casing, cut @ 2618', POH. LD 83 jts and a cut off.

3-20-14 RIH to 2668', pump 120 sx plug, POH, WOC. RIH, tag @ 2432', 236' plug. Pump 75 sx @ 2432', POH, WOC. SDON.

3-21-14 RIH, tag @ 2333', 335' total plug, POH to 1022', pump 75 sx, POH, WOC. RIH, tag @ 848', POH to 402', pump 20 sx plug, POH to 60', pump 20 sx, circ to Surface. Cut off wellhead, install Dry Hole plate, cut off anchors, clean location. RD and move out.

Will notify OCD when location is rehabilitated and re-seeded.

Approved for plugging of well bore only.  
 Liability under bond is retained pending receipt  
 of C-103 (Subsequent Report of Well Plugging)  
 which may be found at OCD Web Page under  
 Forms, [www.enr.state.nm.us/oed](http://www.enr.state.nm.us/oed).

RECEIVED

APR 07 2014

NMOCD ARTESIA

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Vice President - Operations

DATE

04-03-2014

Type or print name

Bruce A. Stubbs

E-mail address:

bastubbs@armstrongenergycorp.com

PHONE:

575-625-2222

For State Use Only

APPROVED BY:

TITLE

Dr. H. D. Spivack

DATE

4/8/14

Conditions of Approval (if any):

Send in Subsequent C-103