

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. JENKINS-B FEDERAL 16
2. Name of Operator COG OPERATING LLC Contact: KANICIA CASTILLO E-Mail: kcastillo@conchoresources.com		9. API Well No. 30-015-32371-00-S1
3a. Address ONE CONCHO CENTER 600 W ILLINOIS AVENUE MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-685-4332	10. Field and Pool, or Exploratory LOCO HILLS-PADDOCK UNKNOWN
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 20 T17S R30E NENW 965FNL 1650FWL		11. County or Parish, and State EDDY COUNTY, NM


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

COG Operating LLC respectfully requests to recompleate to the San Andres.

Rod Pull Procedure
? MIRU WSU, NU BOP
? POOH w/ rods and pump on LD on location
o Let Engineering know the quantity and conditions of the rods and pump
? RU Wireline
? Set CIBP @ 4221?
? Wireline truck dump 40? Class C cement of top of CIBP
? Tag cement plug to verify depth of 4181?
? Pull up 4? to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer corrosion inhibitor.



Accepted for record
NMOC D 105
5-20-14

submit C-102 to NMOC D

14. I hereby certify that the foregoing is true and correct. Electronic Submission #241591 verified by the BLM Well Information System For COG OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by JENNIFER MASON on 05/06/2014 (14JAM0344SE)		APPROVED MAY 9 2014 <i>[Signature]</i>
Name (Printed/Typed) KANICIA CASTILLO	Title PREPARER	
Signature (Electronic Submission)	Date 04/08/2014	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		
Approved By _____	Title _____	Date _____
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office _____		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #241591 that would not fit on the form

32. Additional remarks, continued

- ? Test Casing to 4,200 psi and report back to engineering if the pressure holds.
- ? Secure wellbore
- ? RDMO WSU

Tentative Recompletion Procedure

- ? NU frac valve, and test casing to 4200 psi
- ? Rig up wireline.
- ? RIH w/ perforating guns and perforate San Andres Zone from 3996?-4122? w/ 3 spf, 60? phasing, 24holes.
- ? Acidize w/ 1500 gals of 15% HCl.
- ? Frac zone w/ 181,250 # of sand.
- ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? Rig up Wireline
- ? RIH w/ WL and set Composite Plug @ 3900?
- ? Perforate San Andres Zone from 3692?-3836? w/ 3 spf, 60? phasing, 24 holes.
- ? Acidize w/ 1500 gals of 15% HCl.
- ? Frac zone w/ 181,250 # of sand.
- ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? MIRU WSU
- ? Rig up Wireline
- ? RIH w/ WL and set Composite Plug @ 3600?
- ? Perforate San Andres Zone from 3078?-3251? w/ 3 spf, 60? phasing, 21 holes.
- ? Acidize w/ 1500 gals of 15% HCl.
- ? Frac zone w/ 181,250 # of sand.
- ? Record ISIP and FG, Get 5, 10, 15 min SIP
- ? RIH with Production tbg and tag for fill w/ bailer at knocked Composite plugs @ 3650? and 3900?
- ? Clean out fill to new PBTD @ 4096?
- ? POOH bailer and tbg
- ? RIH with production tubing and locate intake at 4125?
- ? Set TAC @ 3050?
- ? RIH w/ rods and pump.
- ? RDMO rig.

COG Operating LLC

Current:

Lease & Well #


Jenkins B Federal # 16

SPUD: 9/8/02
3001532371

Sec 20C, 17S, 30E, Eddy Co., NM

Elevation - 3632

KB -



COG Operating LLC

Projected:

Lease & Well #


Jenkins B Federal # 16

SPUD: 9/8/02
3001532371

Sec 20C, 17S, 30E, Eddy Co., NM

Elevation - 3632

KB -



Rod Pull Procedure

- MIRU WSU, NU BOP
- POOH w/ rods and pump on LD on location
 - Let Engineering know the quantity and conditions of the rods and pump
- RU Wireline
- Set CIBP @ 4221'
- Wireline truck dump 40' Class C cement of top of CIBP
- Tag cement plug to verify depth of 4181'
- Pull up 4' to circulate hole clean with fresh water, and displace w/ 2% KCL and 1% packer corrosion inhibitor.
- Test Casing to 4,200 psi and report back to engineering if the pressure holds.
- Secure wellbore
- RDMO WSU

Tentative Recompletion Procedure

- NU frac valve, and test casing to 4200 psi
- Rig up wireline.
- RIH w/ perforating guns and perforate San Andres Zone from 3996'-4122' w/ 3 spf, 60° phasing, 24holes.
- Acidize w/ 1500 gals of 15% HCl.
- Frac zone w/ 181,250 # of sand.
- Record ISIP and FG, Get 5, 10, 15 min SIP
- Rig up Wireline
- RIH w/ WL and set Composite Plug @ 3900'
- Perforate San Andres Zone from 3692'-3836' w/ 3 spf, 60° phasing, 24 holes.
- Acidize w/ 1500 gals of 15% HCl.
- Frac zone w/ 181,250 # of sand.
- Record ISIP and FG, Get 5, 10, 15 min SIP
- MIRU WSU
- Rig up Wireline
- RIH w/ WL and set Composite Plug @ 3600'
- Perforate San Andres Zone from 3078'-3251' w/ 3 spf, 60° phasing, 21 holes.
- Acidize w/ 1500 gals of 15% HCl.
- Frac zone w/ 181,250 # of sand.
- Record ISIP and FG, Get 5, 10, 15 min SIP
- RIH with Production tbg and tag for fill w/ bailer at knocked Composite plugs @ 3650' and 3900'
- Clean out fill to new PBTD @ 4096'
- POOH bailer and tbg
- RIH with production tubing and locate intake at 4125'.
- Set TAC @ 3050'
- RIH w/ rods and pump.
- RDMO rig.

**Jenkins B Federal 16
30-015-32371
COG Operating, LLC.
May 09, 2014
Conditions of Approval**

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 09, 2014.

- 1. Operator shall set a CIBP at 4,221' and dump 40' Class C cement on top. Tag required at a minimum of 4,181'. Additional cement shall be added at a later date to properly plug back the well.**
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.**
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.**
- 4. Surface disturbance beyond the originally approved pad must have prior approval.**
- 5. Closed loop system required.**
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.**
- 7. Operator to have H2S monitoring equipment on location.**
- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.**

9. Subsequent sundry required detailing work done and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
10. See attached for general requirements.

JAM 050914

BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement.

Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class "C"**, for up to 7,500 feet of depth or **Neat Class "H"**, for deeper than 7,500 feet plugs.

6. **Subsequent Plug back Reporting:** Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.**

7. **Trash:** All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.