E SUNDRY Do not use th	UNITED STATES EPARTMENT OF THE INTE BUREAU OF LAND MANAGEN NOTICES AND REPORT nis form for proposals to dri ell. Use form 3160-3 (APD) f	MENT S ON WELLS Il or to re-enter an	D Artesia	OMB	7A	
SUBMIT IN TRIPLICATE - Other instructions on reverse side. I. Type of Well Soil Well Gas Well Other				 If Unit or CA/Agreement, Name and/or No. 891000558X 		
			8. Well Name JAMES RA		and No. ANCH UNIT DI 1 135H	
2. Name of Operator BOPCO LP Contact: LESLIE BARNES E-Mail: lbarnes@basspet.com				9. API Well No. 30-015-42376-00-X1		
3a. Address P O BOX 2760 MIDLAND, TX 79702		 Phone No. (include area code h: 432-221-7341 	2)	10. Field and Pool, QUAHADA R		
4. Location of Well <i>(Footage, Sec.,</i> Sec 21 T22S R30E SENE 15 32.225023 N Lat, 103.52523			11. County or Parish, and State EDDY COUNTY, NM			
12. CHECK APP	PROPRIATE BOX(ES) TO IN	IDICATE NATURE OF	NOTICE, RI	EPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION		. ТҮРЕ О	F ACTION	۷		
 Notice of Intent Subsequent Report Final Abandonment Notice 	 Acidize Alter Casing Casing Repair Change Plans Convert to Injection 	 Deepen Fracture Treat New Construction Plug and Abandon Plug Back 	☐ Reclam ☐ Recomp	lete arily Abandon	 Water Shut-Off Well Integrity Other 	
Attach the Bond under which the w following completion of the involve testing has been completed. Final A determined that the site is ready for This is a post job report of th casing cement job. No ceme was ran which showed TOC the 1? tubing connections, a casing and the ID of the 13-3 performed without success in casing. The first bullhead wa Cement (14.2 ppg, 1.68 cuft/ 1.33 cuft/sk). A second temp sks (45 bbl) Thixotropic Cem psi. Pressure fell off to 350 p	nally or recomplete horizontally, give ork will be performed or provide the doperations. If the operation results bandonment Notices shall be filed or final inspection.) e remedial cement jobs perfor ent was returned to surface on at 284?. A top job utilizing 1? nd low annular clearance betw 3/8? casing. An attempt to fill t ndicating the loss zone was sti as performed as follows: Pump sk), followed by Tail: 605 sks (o log was ran. The second bui tent (14.2 ppg, 1.68 cuft/sk). F posi in 15 min and 270 psi in 30 is 303? of overlap inside of the	subsurface locations and meas Bond No. on file with BLM/BI in a multiple completion or rec nly after all requirements, inclu med on the 9-5/8?, 40#, . the primary cement job. tubing was not possible of veen the OD of the collars the 13-3/8? x 9-5/8? annu II open beneath the shoe o Lead: 150 sks (45 bbls) (143 bbl) Class ?C? Cem lihead was performed as Perform pressure test on a min. A cement bond log	ured and true ve A. Required sul completion in a r ding reclamation J-55, LTC A temperatu due to the OE on the 9-5/8 ilus was of the 13-3/8 Thixotropic ent (14.8 ppg follows: Pum annulus to 50 was then rai	rtical depths of all persequent reports shall be unterval, a Form 3, a have been complete a form 3 and a fore	rtinent markers and zones. be filed within 30 days 3160-4 shall be filed once	
-	Electronic Submission #249 For BOP itted to AFMSS for processing BARNES	CO LP, sent to the Carlsb by CHRISTOPHER WALLS	ad	4 (14CRW0295SE)		
LEOLIE		· · ·				
	Submission)	Date 06/13/2	2014			
	Submission) THIS SPACE FOR	Date 06/13/2		SE		
	THIS SPACE FOR ALLS ed. Approval of this notice does not quitable title to those rights in the sub	FEDERAL OR STATE	OFFICE U		Date 06/13/2014	

BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED

Additional data for EC transaction #249626 that would not fit on the form

32. Additional remarks, continued

Chris Walls with the BLM, a pressure gauge will be installed for the life of the well to monitor for abnormal pressure in the 13-3/8? \times 9-5/8? annulus. The BLM will be notified of any abnormal pressure increases in the annulus.