

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

2 RP-1197

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod Suite 704 Carlsbad, N.M.	Telephone No. 432-556-8730	
Facility Name: Poker Lake Unit Pierce Canyon 5 State No. 1H	Facility Type: E & P	
Surface Owner State of NM	Mineral Owner State of NM	API No. 30-015-36998


LOCATION OF RELEASE

Unit Letter P	Section 5	Township 25S	Range 30E	Feet from the 398	North/South Line South	Feet from 350	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	------------------	------------------------	-------------

Latitude 32.215518 Longitude -103.894893

NATURE OF RELEASE

Type of Release: Produced water/oil	Volume of Release 10 bbls/15 Bbls of crude oil	Volume Recovered 0/0
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 05/25/12 at approximately 10:00 AM	Date and Hour of Discovery 05/25/12 11:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and State Land Office Andrew Kramer	
By Whom? Brian Wall	Date and Hour: 09/06/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.* NA		



Describe Cause of Problem and Remedial Action Taken.*
The flow line developed a leak due to the internal corrosion. A temporary repair clamp was placed on the pipe. One joint of pipe was replaced on 05/30/12
DFSI was retained to remediate the site.

Describe Area Affected and Cleanup Action Taken.*
Approximately 675 sq. ft. of caliche road wand approximately 480 sq. ft. of pasture land. All of the released fluids were absorbed into the grounds. All
remediation activities performed on behalf of BOPCO were in accordance with NMOCD and BLM compliance.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other
federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: <i>Harlan</i>	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: 6/10/14	Expiration Date: NA
E-mail Address: TASavoie@BassPet.com		Conditions of Approval:	
Date: 6/9/14 05/05/2014 Phone: 432-556-8730		Attached <input type="checkbox"/> Final	

* Attach Additional Sheets If Necessary

2RP-1197