


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nHMP1420227087

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: **OXY USA Limited Partnership** 192468 Contact: **Chris Jones**
Address: **102 S. Main St. Carlsbad, NM 88220** Telephone No.: **575-628-4121**
Facility Name: **Government R Federal #2** Facility Type: **Well**

Surface Owner: **Federal** Mineral Owner: API No.: **30-015-28391**

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	14	20S	28E	2310'	South	2310	West	Eddy

Latitude **32.572760 N** Longitude **-104.149283 W**

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls Oil & 170 bbls PW	Volume Recovered: 0 bbls
Source of Release: Gasket on Heater Treater failure	Date and Hour of Occurrence: 7/7/2014	Date and Hour of Discovery: 7/7/2014; 7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher @ NMOC D Jim Amos @ BLM	
By Whom? Chris Jones	Date and Hour: 7/8/2014 12:55 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A gasket failure on the heater treater caused 20 barrels of oil and 170 barrels of produced water to be released. No fluids were recovered. Talon/LPE was contracted to perform an initial site assessment and soil sampling.**

Describe Area Affected and Cleanup Action Taken.*
The release flowed northwest across the location and flowed off location approximately 15' in to the pasture. The overspray area measures approximately 230' long by 35' wide.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION	
Signature: Chris Jones	Approved by Environmental Specialist:
Printed Name: Chris Jones	Approval Date: 7/21/14 Expiration Date: NA
Title: HES Specialist	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION
E-mail Address: Christopher.Jones@oxy.com	Attached <input type="checkbox"/>
Date: 7/10/2014 Phone: 575-628-4121	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

8/21/14

2RP-2380