Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMLC055264

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				NMLC055264			
				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well				8. Well Name and No. JACKSON B 62			
				9. API Well No.		·	
BURNETT OIL COMPANY INC E-Mail: lgarvis@burnettoil.com				30-015-41279-00-X1			
3a. Address 801 CHERRY STREET UNIT FORT WORTH, TX 76102-68	Phone No. (include area code) 817-332-5108		10. Field and Pool, or Exploratory CEDAR LAKE				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State			
Sec 12 T17S R30E NENE 990FNL 330FEL 32.853405 N Lat, 103.917350 W Lon				EDDY COUNTY, NM			
12. CHECK APPE	ROPRIATE BOX(ES) TO INC	DICATE NATURE OF N	OTICE, RE	PORT, OR OTHE	R DATA		
TYPE OF SUBMISSION	TYPE OF ACTION						
	☐ Acidize	☐ Deepen	Production	on (Start/Resume)	☐ Water Shut-Off		
Notice of Intent ∴	☐ Alter Casing	☐ Fracture Treat	☐ Reclama	tion	■ Well Integrity		
☐ Subsequent Report	Casing Repair	☐ New Construction	☐ Recompl	ete	⊠ Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	□ Tempora	rily Abandon	Change PD	to Original A	
•	☐ Convert to Injection	□ Plug Back	☐ Water D	isposal			
Burnett requests a variance to the 7? production casing. The will is checked personally without issues and that the fluthe casing above the TOC will Burnett requests a variance to frac pressure to be 3500 psi. See the summary below of dri	inal inspection.) If the approved APD requiring of plan of action is to complete to by by a lease operator once ever id level is near the insert pump not have fluid sitting inside of immediate perforating and circulating events regarding circulating to the property of	y after all requirements, includ cement be circulated to so the well as discussed believed and to make sure it is at the perforations. Cor it. Culating cement from TO and fluids/cement in the ways after the performance of	urface behindow. producing producin	have been completed, NM O d Max ACCE	and the oper	SERVATION ISTRICT 2014 VED OF The Control Of The Control	
14. I hereby certify that the foregoing is	Electronic Submission #25304	8 verified by the BLM Wel	I Information	System			
Comr	nitted to AFMSS for processing	COMPANY INC, sent to the by DUNCAN WHITLOCK o		(14DW0183SE)		•	
Name (Printed/Typed) LESLIE G	Title REGUL	ATORY CO	DRDINATOR				
Signature (Electronic S		Date 07/15/2		DDOVE	1	·	
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE	PROVE	$\frac{1}{2}$		
Approved By (BLM Approver Not Conditions of approval, if any, are attache certify that the applicant holds legal or eq			JUL 17 2014	Da	e 07/17/2014		
which would entitle the applicant to condu	ict operations thereon.	Office Carlsbac		SLEY W INGRA			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crime statements or representations as to any	for any person knowingly and matter within its jurisdiction.	willfully period	KOPENADENGIN	4 Francis	le United	

Additional data for EC transaction #253048 that would not fit on the form

32. Additional remarks, continued

This well was spudded 6-4-13 and 10.75? 32.75# casing was set at 485? and cement was circulated to surface. After WOC, drilling out from surface casing was begun with immediate loss of all circulation at 486?. Thirteen (13) days later the TD of 6088? was reached. 7? 23# casing was set at 6088?, with a DV tool set at 2940?. A two (2) stage cement job was pumped. Stage one was pumped with 500 sx premium class H cmt, 52 sx circulated to surface. Stage two was pumped with 3500 sx premium lite cmt and was not circulated. BLM was notified (Cheryl de Montigny) that cmt did not circulate. The most likely cause of the lack of cement circulated to surface is the lost circulation zone at 486?.

A Schlumberger Isolation Scanner log was run on 6-12-14 with a summary of results as follows:

Interval Cement Description
TD 6,088? ? 3,692? Good Cement
3,692? ? 3,651? Patchy solids
3,651? ? 2,934? Mostly Gel or liquid
2,934? DV Tool
2,934? ? 2,137? Good Cement
2,137? ? 474? Mixed cement bond response
474? (485? KB) 10.75? srfc csg set w/ Cement to Surface
198? Top of Cement

This log was presented and discussed at a meeting with the BLM in Carlsbad on 7/9/2014. Copies of the Isolation Scanner Cement Evaluation Report were provided to the BLM at this meeting.

The completion has not begun yet. Burnett plans to complete three (3) separate intervals in the Yeso formation. The upper most perforation will be at 4,626?. One zone will be completed at a time, produced for approximately 120 days via sub pump, set RBP, move up hole and repeat until all three zones are completed. When the Paddock pumps off after completion, all RBP?s will be pulled and the three (3) Yeso Pool intervals will be downhole commingled and rod pumped.

Proposed perforations:

Stage 1: Basal Blinebry 5974, 5936, 5916, 5892, 5850, 5840, 5822, 5775, 5758, 5750, 5688, 5676, 5660, 5632, 5620, 5608, 5580, 5538. 18 intervals at 2 SPF.

Stage 2: Upper Blinebry 5406, 5364, 5356, 5344, 5336, 5280, 5265, 5250, 5240, 5193, 5184, 5164, 5152, 5134, 5114, 5096, 5086, 5074, 5044, 5030, 4982, 4956. 22 intervals at 2 SPF.

Stage 3: Paddock 4848, 4841, 4833, 4820, 4810, 4796, 4784, 4776, 4746, 4720, 4691, 4654, 4648, 4638, 4626. 15 intervals at 3 SPF.

At such time as the well is P&A?d, the 7? casing will be pulled from +/-198?, or perforated at +/-198? and cemented to surface.

See Attached CBL