

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

AUG 01 2014

Form C-141  
Revised August 8, 2011

NMOCD AF 15510  
Submit Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1422438444

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Oxy Permian Ltd. <u>1160911</u>	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Pure Gold A Federal #5	Facility Type	Well location
Surface Owner	BLM	Mineral Owner	API No. 30-015-35292

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	23S	31E	2040	South	1980	West	Eddy County, NM

Latitude N 32.28827° Longitude W 103.78489°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	15 bbls oil, 20 bbls water	Volume Recovered	0 bbls
Source of Release	Stuffing box leak on well head	Date and Hour of Occurrence	07/17/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Sol Hughes, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	07/18/2014 @ 9:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The packing in the stuffing box on the well head was compromised and leaked 15 bbls of oil and 20 bbls of produced water onto the ground. No fluids were recovered and the packing in the stuffing box was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 150' x 40' both on and off location. The leak is mostly on the pad around and south of the well head with some overspray reaching into the pasture on the north side of the location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers	Signed By <u>M/14 Bratcher</u> Approved by Environmental Specialist.	
Title: HES Advisor	Approval Date: <u>8/12/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Chancey.Summers@oxy.com</u>	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	
Date: <u>7-21-14</u> Phone: (575) 397-8216	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

9/12/14

2RP-2432