Form 3160-5 (August 2007) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Scrial No. NMNM54290 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well				8. Well Name and No		
☑ Oil Well				NORTH BRUSHY DRAW FEDERAL 35 9		
2. Name of Operator Contact: HEATHER BREHM RKI EXPLORATION & PRODUCTION E-Mail: hbrehm@rkixp.com				9. API Well No. 30-015-42220		
3a. Address         3b. Phone No. (           210 PARK AVENUE, SUITE 900         Ph: 405-996           OKLAHOMA CITY, OK 73102         Fx: 405-996-			ea code)	10. Field and Pool, or Exploratory CORRAL CANYON;BONE SPR,S		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) <b>ZF</b> Sec 35 T25S R30E Mer NMP NENE 300FNL 260FEL 32.053384 N Lat, 103.565029 W Lon				11. County or Parish, and State EDDY COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, F	REPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> </ul>	<ul> <li>Acidize</li> <li>Alter Casing</li> </ul>	Deepen Fracture Treat	Reclar		□ Water Shut-Off □ Well Integrity	
Final Abandonment Notice	<ul> <li>Casing Repair</li> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	<ul> <li>New Construct</li> <li>Plug and Aban</li> <li>Plug Back</li> </ul>	—	orarily Abandon	y Abandon Drilling Operations	
<ul> <li>13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for</li> <li>COMPLETION SUNDRY Began completion activites on 5/ DV tool at 4936' PBTD at 13,418 5/16/14 Perf 13,216'-13,218', 13 5/22/14 Frac&amp;Perf 9,496'-13,366 TOTAL 20/40 WHITE SAND = 2 TOTAL 20/40 WHITE SAND = 2 TOTAL 20/40 SUPER LC = 483, TOTAL SAND = 2,883,309 LBS LOAD TO RECOVER = 53,630 E 5/27/14 Drill out plugs 5/29/14 Flowback Well is Producing.</li> <li>14. Thereby certify that the foregoing in Name (Printed/Typed) HEATHE</li> </ul>	ally or recomplete horizontally, gi ork will be performed or provide th d operations. If the operation resul bandonment Notices shall be filed final inspection.) 9/2014 9	ve subsurface locations ar e Bond No. on file with B Its in a multiple completio only after all requirement nes to 9,000 psig-OK 13,366'-13,368' at 4 SP Accepted A 20 NM	In measured and true of LM/BIA. Required s n or recompletion in a s, including reclamati	vertical depths of all perti ubsequent reports shall be a new interval, a Form 31 on, have been completed, <b>NM OIL C</b> <i>ARTES</i> <i>AUG</i> <b>RECE</b> on System ad	nent markers and zones. e filed within 30 days 60-4 shall be filed once	
			CEGULATORT AL		·	
Signature (Electronic	Submission)		6/04/2014			
	THIS SPACE FOR	R FEDERAL OR S	TATE OFFICE L	JSE		
Approved By					Date	

.

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* `