Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

NMNM0144698

abandoned we	II. Use form 3160-3 (APD) for :	such proposals.		J. II maini, Anottee		
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No.					
Type of Well	ner			8. Well Name and No SAVAGE 5 EH F		
Name of Operator     MEWBOURNE OIL COMPAN	Contact: JACKI Y E-Mail: jlathan@mewbour			9. API Well No. 30-015-41897-	00-X1	
3a. Address P O BOX 5270 HOBBS, NM 88241	3b. Pl Ph:	hone No. (include area code) 575-393-5905		10. Field and Pool, or Exploratory WINCHESTER		
4. Location of Well (Footage, Sec., T	11. County or Parish	11. County or Parish, and State				
Sec 6 T20S R29E SENE 2250 32.603974 N Lat, 104.105937				EDDY COUNT	Y, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO INDI	CATE NATURE OF 1	NOTICE, R	LEPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION		TYPE OF	FACTION		:	
☐ Notice of Intent	☐ Acidize	☐ Deepen	epen 🔲 Produc		ction (Start/Resume)	
	_ ~	☐ Fracture Treat	☐ Reclan		□ Well Integrity	
Subsequent Report     ■	- ~	☐ New Construction	☐ Recom	•	· <b>⊠</b> Other ∵ Well Spud	
☐ Final Abandonment Notice		☐ Plug and Abandon		rarily Abandon	Wen Space	
	☐ Convert to Injection	☐ Plug Back	■ Water	Disposal .		
determined that the site is ready for f	pandonment Notices shall be filed only a inal inspection.) 110. Ran 1110' of 13 3/8" 48# H Mixed @ 12.5 #/g w/2.11 yd. Tai n @ 3:45 PM 02/11/14. Circ 133 to 1250# for 30 minutes, held O	-	-		•	
Bond on file: NM1693 nationw		SEP 1 7 20	14			
	ox second CD 9-17-2014	RECEIVED		SEP 1	3 2014.	
14. I hereby certify that the foregoing is	Electronic Submission #238579	LCOMPANY, sent to the	e Carlsbad_	n SystemARLSBAD	FIELD OFFICE	
Name (Printed/Typed) JACKIE L	ATHAN	Title AUTHO	RIZEDRE	RESENTATIVE		
					•	
Signature (Electronic S	THIS SPACE FOR FE	Date 03/12/20	···	ISE	·	
	THO OF AGET ON TE	DENAL ON STATE	OTTIOE C	,OL.		
Approved By		Title			Date	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant th	itable title to those rights in the subject					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for statements or representations as to any n	or any person knowingly and	willfully to n	nake to any department o	r agency of the United	

## Revisions to Operator-Submitted EC Data for Sundry Notice #238579

## **Operator Submitted**

Sundry Type:

SPUD

SR

Lease:

NMNM0144698

Agreement:

Operator:

MEWBOURNE OIL COMPANY PO BOX 5270 HOBBS, NM 88241 Ph: 575-393-5905

Admin Contact:

JACKIE LATHAN AUTHORIZED REPRESENTATIVE E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905

**Tech Contact:** 

JACKIE LATHAN AUTHORIZED REPRESENTATIVE E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905

Location:

State: County: NM EDDY

Field/Pool:

WINCHESTER BONE SPRING

Well/Facility:

SAVAGE 5 EH FEDERAL 1H Sec 6 T20S R29E SENE 2250FNL 200FEL

**BLM Revised (AFMSS)** 

SPUD SR

NMNM0144698

MEWBOURNE OIL COMPANY P O BOX 5270 HOBBS, NM 88241 Ph: 575.393.5905

JACKIE LATHAN AUTHORIZED REPRESENTATIVE E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905

JACKIE LATHAN AUTHORIZED REPRESENTATIVE

E-Mail: jlathan@mewbourne.com

Ph: 575-393-5905

NM EDDY

WINCHESTER

SAVAGE 5 EH FEDERAL 1H Sec 6 T20S R29E SENE 2250FNL 0200FEL 32.603974 N Lat, 104.105937 W Lon




WELDING • BOP TESTING
NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Pa	<i>l</i>	of	1	", <b>"</b>
	Table 1 Page 1		20. 57.73.1	
	<b>73</b> /			· 🐧 "

	Loyington, NM • 575-395-4540	3, 1
company: Mewbourne Oil	Date: 2-12-14	Invoice # 60348
Lease: SAVIAGE SEH FE/#	Drilling Contractor: Talter	504 Rig# 46
Plug Size &Type: N/A	orill Pipe Size 4/12 XH Tester:	PAUL ALVAGADO
Required BOP: 3M	Installed BOP: 5 M	An nother
Required both and the second s		

Appropriate Casing Valve Must Be Open During BOP Test

-



S. Lake	Chillian Land Town of the Street of the	S. Harris . P.			And the second of the second o
TEST 0	A TIEMS TESTED	TEST LENGTH	/LOW PSI	HIGH PSI	REMARKS
	TABLE KIRLEY	10/10	aso	3000	oK
a	<b>18</b>		250	3000	oK .
3	l g		250	3000	ok /
4			Transmitted	3000	The control of the co
.5	17. San Fire San	10/10	250	3000	oK
6	1,6.2.8	10/10	250	3000	oK .
70	354.8	10/10-1	286	3000	o K
27 14 25 7 166	25,26,68	Bump			
7925 44.03	9, 11, 15, CSG	30/30	27,500	20.00	小して、これには、これには、これには、これには、「は、これを持ちなった。」という。 これには、これには、これには、これには、これには、これには、これには、これには、
	810/15 CSG	3 %/3.0		1256	계속 하는 바로 가는 그는 그는 그들은 그는 가는 그를 하는 것 같아. 그는 그를 하는 것 같아. 그는 그는 그를 하는 것 같아.
11/2	3.5,480,511,65	30/30	- 3/2	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	
/又	8\$/11/15	70/30	2.50	1250	6.6
			* * * * * * * * * * * * * * * * * * *	N Nº 1	
		West and		34 3524	
		in the second		\$ 5-3° ×	
				3 33	
		<u> </u>		\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	
		*			
			<u> </u>		

Com	bany Mewborene		Date	2-12-	14	
	SAVASE SEHT					· · · · · · · · · · · · · · · · · · ·
	ng Contractor Patters			,	NI /id	4/2 XH
istani)	ing Contractor FASTAS	OM:	1 lug & 1	//// // Co		1450
Accur	nulator Pressure: 2600					
	and the second s	nulator Fur				• *
To Ch	eck-USABLE FLUID II	NEHE NETROG	EN BOTT	LES (III.A	.2.c.i. or ii or ii	i) .
•	Make sure all rams and an Ensure accumulator is pu					
Ž,	1. Open HCR Valve. (If	applicable)		A SECTION AND A		7- 7-*. 4-**
	2. Close annular.	÷ .				pec
i	<ul><li>3. Close all pipe rams.</li><li>4. Open one set of the pipe.</li></ul>	ne rams to simula	te closing t	he blind ram.		* 14.4 *
. 4	5. Record remaining press	7.4	2.			required.
	a. {1285 psi for a 1500	* * * * * * * * * * * * * * * * * * * *	·		<u>.</u>	
	6. If annular is closed, oper				rem) e (1200 h	isi xui: a suud aysi
, in			An and a second second	on in Some some in the end	in film. Managaran sangaran dan sangaran	ا ورزان درخوره بسه در الاردور الموتر
	Start with manifold pressure.  1. Open bleed line to the 2. Close bleed line. Bare 3. Record pressure drop Minimum: a [700 psi fo	tank, slowly. (ga ly bump electric psi. T	b. (1100 uge needle pump and sest fails if)	psi for 2000 at will drop at ee what pressore drop	and 3000 psi sy the lowest bourse the needle ps below mining	vstem) t <b>tle pressure)</b> jumps up to. mum.
To Ch	eck - THE CAPACITY O	F THE ACCUM	ULATOR	PUMPS (III	.A.2.f.)	
•	Isolate the accumulator be	ottles or spherical	from the p	umps & mani	fold.	
0	Open the bleed off valve t	o the tank, {man	fold psi she	ould go to 0 p	si) close bleed	i valve.
	<ol> <li>Open the HCR valve,</li> <li>Close annular</li> <li>With pumps only, time</li> <li>Record elapsed time</li> <li>a. {950 psi for a 1</li> </ol>	how long it take	fails if it ta	kes over 2 m	inutes.	
	•	oo har ayarem?	n. Trang	positor a 2000	Dood par ay	
5	Signed: anager Signed		engen anne general et en g General et en general et e	-		
~			·			

