

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received
10/9/14

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ALAMO PERMIAN RESOURCES, LLC	Contact	RICKY RODRIGUEZ
Address	415 W. WALL ST. SUITE 500	Telephone No.	575 703 6425
Facility Name:	FEDERAL S 6	Facility Type:	WELL
Surface Owner	FEDERAL	Mineral Owner	
		API No.	30-15-20147

LOCATION OF RELEASE

Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
28	17S	30E	1980	S	1980	W	EDDY

Latitude 32°48'13.46"N
Longitude -103°58'44.74"W

NATURE OF RELEASE

Type of Release:	OIL	Volume of Release:	10 BBLS	Volume Recovered:	NONE
Source of Release:	TRANSITION IN POLY LINE	Date and Hour of Occurrence:	JAN 08, 2014	Date and Hour of Discovery	JAN 08, 2014; 11:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER via phone call; JIM AMOS via phone call		
By Whom?	Carie Stoker	Date and Hour	JAN 08, 2014, 12:00 P.M.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Cause of Problem: A transition in a section of the poly line busted.

Remedial Action Taken: Dispatched backhoe to scrape up leak affected area; spread fresh earth

Describe Area Affected and Cleanup Action Taken.*

Area Affected: Leak affected area is on well site pad

INITIAL Cleanup action: Scraping and removal of the leak affected area; laid fresh earth; scheduled sampling of leak affected area

ADDITIONAL Cleanup action: Lines were hand spotted and the impacted soil around the well head was hand excavated as well. The impacted area on the pad and behind the pad were excavated to a depth of 1' BGS. The material was stockpiled and then transported to disposal. Fresh backfill was spread on the excavated area. The area was brought back to grade and compacted with the back-hoe.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Carie Stoker</i>	OIL CONSERVATION DIVISION	
Printed Name: CARIE STOKER	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: REGULATORY AFFAIRS COORDINATOR	Approval Date: 10/15/14	Expiration Date: NA
E-mail Address: carie@stokeroilfield.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 10/09/2014	Phone: 432 664 7659	

* Attach Additional Sheets If Necessary

2RP-2157