


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

0 AB143 235 3445

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <u>Devon Energy Production</u> <u>6137</u>	Contact <u>Daniel Suniga- Devon Production Foreman</u>
Address <u>6488 Seven Rivers Hwy Artesia, NM 88220</u>	Telephone No. <u>575-390-5850</u>
Facility Name <u>Todd 26G Fed 2 SWD</u>	Facility Type <u>Salt Water Disposal</u>

Surface Owner <u>Federal</u>	Mineral Owner <u>Federal</u>	API No. <u>30-015-20277</u>
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	S26	T23S	R31E	1980	FNL	1650	FEL	Eddy

Latitude: 32.277191377827 Longitude: -103.745412550316

NATURE OF RELEASE

Type of Release Spill <u>Oil</u>	Volume of Release <u>45 bbls oil</u>	Volume Recovered <u>40bbls oil</u>
Source of Release <u>Oil tank overflow</u>	Date and Hour of Occurrence <u>November 09, 2014 ~8:30 AM</u>	Date and Hour of Discovery <u>November 09, 2014 9:00 AM</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Mike Bratcher- OCD</u> <u>Jeff Robertson- BLM</u>	
By Whom? <u>Wesley Ryan- Devon Assistant Production Foreman</u>	Date and Hour <u>November 10, 2014 11:21 AM; November 11, 2014 3:00 PM</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse <u>N/A</u>	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

The DR-120-24V power supply that provides 24 VDC to the PLC failed and a loss of power occurred at the Todd 26G Fed 2 SWD that led to a spill of 45 bbls of oil. As a result of the power outage pumps and alarms lost power and communication with each other. The faulty unit was replaced and power was restored to the PLC.

Describe Area Affected and Cleanup Action Taken.*

A 60'x20' area of the pad at the Northwest side near the storage tanks inside the berm containment was affected by the spill requiring the aid of a vacuum truck provided by Standard Energy Services. 40 bbls of the 45 bbls of oil spilled were recovered. The contaminated caliche will be removed and replaced with clean caliche.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Yuri Fernandez</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Yuri Fernandez</u>	Approved by Environment <u>Signed By Mike Bratcher</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>11/19/14</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Yuri.Fernandez@dvn.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	
Date: <u>November 11, 2014</u> Phone: <u>575.748.1846</u>	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN: 12/19/14

2RP-2611