

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

NOV 21 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

0AB143252641 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production <u>4137</u>	Contact Daniel Suniga- Devon Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5850
Facility Name North Pure Gold 10J Fed 10	Facility Type: Oil

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-33386
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	10	23S	31E	2130	SOUTH	1980	EAST	EDDY

Latitude: 32.3175219530467 Longitude: -103.763586846606

NATURE OF RELEASE

Type of Release Spill: Produced Water	Volume of Release 600 bbls pw	Volume Recovered 0 bbls pw
Source of Release: Ruptured line	Date and Hour of Occurrence November 18, 2014 8:30 AM	Date and Hour of Discovery November 18, 2014 8:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson- BLM Mike Bratcher- OCD	
By Whom? Kevin Phillips- Devon Assistant Production Foreman	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

A polyline was run over causing it to rupture and release produced water at the North Pure Gold 10J Fed 10. The line was isolated and repaired.

Describe Area Affected and Cleanup Action Taken.*

A tract of approximately 4' x 1500' was affected by the produced water. Environmental cleanup is being coordinated with Talon to address the affected soil. No water was able to be recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Yuri Fernandez</u>	OIL CONSERVATION DIVISION	
Printed Name: Yuri Fernandez	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Field Admin Support	Approval Date: <u>11/21/14</u>	Expiration Date: <u>NA</u>
E-mail Address: Yuri.Fernandez@dvn.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: November 20, 2014 Phone: 575.748.1846	SUBMIT REMEDIATION PROPOSAL NO. <u>1212114</u>	

* Attach Additional Sheets If Necessary

LATER THAN: 12/21/14

2RP-2621