
Form 3160-5		UNITED STATES						
(August 2007)	DE BU	UNITED STATE PARTMENT OF THE I JREAU OF LAND MANA	NOV 07 2014		OMB NO. 1004-0135 Expires: July 31, 2010			
SUNDRY NOTICES AND REPORTS ON W Do not use this form for proposals to drill or to re abandoned well. Use form 3160-3 (APD) for such			ELLS		5. Lease Serial No. NMNM124655			
abar	proposals.		6. If Indian, Allottee or Tribe Name					
SUBMIT IN TRIPLICATE - Other instructions on rev				verse side.	··· 3··· .	7. If Unit or CA/Agre NMNM127417	ement, Name and/or No.	
1. Type of Well 🔲 Gas Well 🔲 Other				· .	_	8. Well Name and No. HAMBONE FEE	COM 1H	
2. Name of Operator Contact: DAVID A EY COG OPERATING LLC E-Mail: DEYLER@MILAGRO-RE				YLER ES.COM		9. API Well No. 30-015-38980-0		
3a. Address ONE CONCHO CI MIDLAND, TX 79		WILLINOIS AVENUE	3b. Phone N Ph: 432-6	o. (include area code 87-3033)	10. Field and Pool, or BRUSHY DRAV	Exploratory N	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish,	and State	
Sec 5 T26S R29E SWSW Lot M 660FSL 330FWL						EDDY COUNTY, NM		
12. CH	IECK APPR	OPRIATE BOX(ES) T	O INDICAT	E NATURE OF 1	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMI	SSION	TYPE OF ACTION						
Notice of Intent		□ Acidize	De 🗌	-	Produc	tion (Start/Resume)	UWater Shut-Off	
Subsequent Repo	rt			acture Treat	— ·	Reclamation 🖸 Well Integrity		
Final Abandonment Notice				w Construction	Recom		Other	
		□ Change Plans ☑ Plu □ Convert to Injection □ Plu				porarily Abandon er Disposal		
determined that the site	leted. Final Ab	andonment Notices shall be fi	led only after al	ple completion or reco l requirements, incluc	ompletion in a	new interval, a Form 316	filed within 30 days 50-4 shall be filed once and the operator has	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS 3) PUMP 25 SXS 4) PUMP 70 SXS 5) CUT X PULL 5- 6) PUMP 40 SXS 7) PUMP 75 SXS 8) MIX X CIRC. TO	leted. Final Ab e is ready for fi CMT. @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 .1/2'' CSG. @ CMT. @ 1,3 CMT. @ 405 O SURF. 25	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8"CSG.SI	led only after al 6,600'-6,425 VOC X TAG (HOE,T/DLWF TUB); WOC) SG SHOE); V	l requirements, incluc V(T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC K TAG CMT. PUL WOC X TAG CM1	wpletion in a ling reclamatio VELL S X TAG. (G. G. F. PLUG.	new interval, a Form 316 n, have been completed, SEE ATTACHE CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS 3) PUMP 25 SXS 4) PUMP 70 SXS 5) CUT X PULL 5- 6) PUMP 40 SXS 7) PUMP 75 SXS 8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR	leted. Final Ab e is ready for fi- P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 405 O SURF. 25 T OFF WELL COCEDURE	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8"CSG.SI 0 +/-1,300'. 55'-1,245'(5-1/2"CSG.SI 5'-250'(T/SALT,13-3/8"C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE	led only after al 6,600'-6,425 /OC X TAG (HOE,T/DLWF TUB); WOC) SG SHOE); V ON STEEL E CLOSED-L(I requirements, incluc V(T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC K TAG CMT. PUL NOC X TAG CMT PLATE TO CSGS	ompletion in a ling reclamation VELL X TAG. G. G. F. PLUG. S. X INSTAL	new interval, a Form 316 n, have been completed, CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA KER.	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS 3) PUMP 25 SXS 4) PUMP 70 SXS 5) CUT X PULL 5- 6) PUMP 40 SXS 7) PUMP 75 SXS 8) MIX X CIRC. TC 9) DIG OUT X CU DURING THIS PR THE REQUIRED I	leted. Final Ab e is ready for fi P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 .1/2" CSG. @ CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WEL! COCEDURE DISPOSAL, I	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); Ŵ 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8"CSG.SI 0 +/-1,300'. 55'-1,245'(5-1/2"CSG.SI SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1/2"CSG.SI 55'-1,245'(5-1	led only after al 6,600'-6,425 /OC X TAG (HOE,T/DLWF TUB); WOC) SG SHOE); V ON STEEL E CLOSED-L(I requirements, incluc V(T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC K TAG CMT. PUL NOC X TAG CMT PLATE TO CSGS	WELL X TAG. G. F. PLUG. S. X INSTAL	new interval, a Form 316 n, have been completed, CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA KER. ONTENTS TO	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS 3) PUMP 25 SXS 4) PUMP 70 SXS 5) CUT X PULL 5- 6) PUMP 40 SXS 7) PUMP 75 SXS 8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR	leted. Final Ab e is ready for fi P @ 6,600', CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELL COCEDURE DISPOSAL, I he foregoing is	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8''CSG.SI 0 +/-1,300'. 55'-1,245'(5-1/2''CSG.S' 5'-250'(T/SALT,13-3/8''C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE PER OCD RULE 19.15. True and correct. Electronic Submission f For COG (ommitted to AFMSS for pr	led only after al 6,600'-6,425 /OC X TAG (HOE, T/DLWF TUB); WOC) SG SHOE); \ ON STEEL CLOSED-L(17. #257601 verifin DPERATING L	I requirements, incluc (T/B.S.); CIRC.V CMT. PLUG. (TAG CMT. PUL WOC X TAG CMT. PLATE TO CSGS OOP SYSTEM W COP SYSTEM W	WELL X TAG. G. F. PLUG. S. X INSTAL A STEEL VA STEEL II Information arlsbad 11/05/2014 (1	new interval, a Form 316 n, have been completed, DEE ATTACHE CONDITIONS	50-4 shall be filed once and the operator has DFOR OF APPROVA KER. ONTENTS TO	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS 3) PUMP 25 SXS 4) PUMP 70 SXS 5) CUT X PULL 5- 6) PUMP 40 SXS 7) PUMP 75 SXS 8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED I	leted. Final Ab e is ready for fi P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELL COCEDURE DISPOSAL, I he foregoing is	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8''CSG.SI 0 +/-1,300'. 55'-1,245'(5-1/2''CSG.S' 5'-250'(T/SALT,13-3/8''C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE PER OCD RULE 19.15. true and correct. Electronic Submission # For COG (ommitted to AFMSS for pr EYLER	led only after al 6,600'-6,425 /OC X TAG (HOE, T/DLWF TUB); WOC) SG SHOE); \ ON STEEL CLOSED-L(17. #257601 verifin DPERATING L	I requirements, includ (T/B.S.); CIRC.V CMT. PLUG. (TAG CMT. PUL WOC X TAG CMT PLATE TO CSGS OOP SYSTEM W COP SYSTEM W COP SYSTEM W COP SYSTEM W COP SYSTEM W	welling reclamation VELL X TAG. () G. F. PLUG. S. X INSTAL A STEEL ACC V/C	new interval, a Form 316 n, have been completed, DEE ATTACHE CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA KER. ONTENTS TO <u>DI JOJY</u> MATION PROCEDUE	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS (3) PUMP 25 SXS (4) PUMP 70 SXS (5) CUT X PULL 5- 6) PUMP 40 SXS (7) PUMP 75 SXS (8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED D	leted. Final Ab e is ready for fi P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. CMT. @ 1,3 CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELI COCEDURE DISPOSAL, I he foregoing is CC DAVID A E	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8''CSG.SI 0 +/-1,300'. 55'-1,245'(5-1/2''CSG.S' 5'-250'(T/SALT,13-3/8''C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE PER OCD RULE 19.15. true and correct. Electronic Submission # For COG (ommitted to AFMSS for pr EYLER	led only after al 6,600'-6,425 /OC X TAG (HOE,T/DLWF TUB); WOC) SG SHOE); V ON STEEL CON STEEL CLOSED-L(17. 257601 verifi DPERATING L rocessing by	I requirements, includ (T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC (TAG CMT. PUL NOC X TAG CMT PLATE TO CSGS OOP SYSTEM W COP SYSTEM W COP SYSTEM W Title AGENT Date 08/19/2	WELL X TAG. G. F. PLUG. S. X INSTAL A STEEL II Information arlsbad 11/05/2014 (1	new interval, a Form 316 n, have been completed, EEE ATTACHE CONDITIONS LL DRY HOLE MARI TANK AND HAUL C CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA KER. ONTENTS TO <u>DI JOJY</u> MATION PROCEDUE	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS. 3) PUMP 25 SXS. 4) PUMP 70 SXS. 5) CUT X PULL 5- 6) PUMP 40 SXS. 7) PUMP 75 SXS. 8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED D 14. I hereby certify that th Name (Printed/Typed) Signature	leted. Final Ab e is ready for fi P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. CMT. @ 1,3 CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELI COCEDURE DISPOSAL, I he foregoing is CC DAVID A E	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8''CSG.SI 9 +/-1,300'. 55'-1,245'(5-1/2''CSG.S' 5'-250'(T/SALT,13-3/8''C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE PER OCD RULE 19.15. True and correct. Electronic Submission # For COG (ommitted to AFMSS for pr EYLER	led only after al 6,600'-6,425 /OC X TAG (HOE,T/DLWF TUB); WOC) SG SHOE); V ON STEEL CON STEEL CLOSED-L(17. 257601 verifi DPERATING L rocessing by	I requirements, includ (T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC (TAG CMT. PUL NOC X TAG CMT PLATE TO CSGS OOP SYSTEM W AMES AMOS on Title AGENT Date 08/19/2 AL OR STATE	WELL X TAG. G. F. PLUG. S. X INSTAL A STEEL II Information arlsbad 11/05/2014 (1	new interval, a Form 316 n, have been completed, EEE ATTACHE CONDITIONS LL DRY HOLE MARI TANK AND HAUL C CONDITIONS	50-4 shall be filed once and the operator has ED FOR OF APPROVA KER. ONTENTS TO MATION PROCEDUR ATTACHED	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS. 3) PUMP 25 SXS. 4) PUMP 70 SXS. 5) CUT X PULL 5- 6) PUMP 40 SXS. 7) PUMP 75 SXS. 8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED D 14. Thereby certify that th Name (Printed/Typed) Signature 	leted. Final Ab e is ready for fi P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELL COCEDURE DISPOSAL, I he foregoing is CCEDURE DISPOSAL, I he foregoing is	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8"CSG.SI 9+/-1,300'. 55'-1,245'(5-1/2"CSG.S' 5'-250'(T/SALT,13-3/8"C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELE WE PLAN TO USE THE PER OCD RULE 19.15. true and correct. Electronic Submission f For COG (committed to AFMSS for pr SYLER ubmission) THIS SPACE F(led only after al 6;600'-6,425 VOC X TAG (HOE, T/DLWF TUB); WOC) SG SHOE); V ON STEEL CLOSED-L(17. 2577601 verific DPERATING L rocessing by A OR FEDER	I requirements, includ (T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC CTAG CMT. PUL WOC X TAG CMT PLATE TO CSGS DOP SYSTEM W Ed by the BLM We LC, sent to the C JAMES AMOS on Title AGENT Date 08/19/2 AL OR STATE	WELL X TAG. G. F. PLUG. S. X INSTAL A STEEL II Information arlsbad 11/05/2014 (1	new interval, a Form 316 n, have been completed, EEE ATTACHE CONDITIONS LL DRY HOLE MARI TANK AND HAUL C CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA KER. ONTENTS TO <u>D / O / J Y</u> MATION PROCEDUR ATTACHED	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS (3) PUMP 25 SXS (4) PUMP 70 SXS (5) CUT X PULL 5- 6) PUMP 40 SXS (7) PUMP 75 SXS (8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED D 14. I hereby certify that th Name (Printed/Typed) Signature 	leted. Final Ab e is ready for final P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELD COCEDURE DISPOSAL, 1 COCEDURE DISPOSAL, 1 he foregoing is CCEDURE DISPOSAL, 1 he foregoing is	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8"CSG.SI 9+/-1,300'. 55'-1,245'(5-1/2"CSG.S' 5'-250'(T/SALT,13-3/8"C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELE WE PLAN TO USE THE PER OCD RULE 19.15. true and correct. Electronic Submission f For COG (committed to AFMSS for pr SYLER ubmission) THIS SPACE F(led only after al 6;600'-6,425 VOC X TAG (HOE, T/DLWF TUB); WOC) SG SHOE); V ON STEEL CLOSED-L(17. 2577601 verific DPERATING L rocessing by A OR FEDER s not warrant or e subject lease	I requirements, incluc (T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC (TAG CMT. PUL WOC X TAG CMT PLATE TO CSGS OOP SYSTEM W COP SYSTEM W C, sent to the C JAMES AMOS on Title AGENT Date 08/19/2 AL OR STATE Office	VELL X TAG. G. C. PLUG. S. X INSTAL / A STEEL // A STEEL	new interval, a Form 316 in, have been completed, EEE ATTACHE CONDITIONS LL DRY HOLE MARI TANK AND HAUL C CONDITIONS	50-4 shall be filed once and the operator has CD FOR OF APPROVA KER. ONTENTS TO DI JOJY MATION PROCEDUR ATTACHED MATION PROCEDUR	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS (3) PUMP 25 SXS (4) PUMP 70 SXS (5) CUT X PULL 5- 6) PUMP 40 SXS (7) PUMP 75 SXS (8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED D 14. I hereby certify that the Name (Printed/Typed) Signature 	leted. Final Ab e is ready for final P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELL COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I he foregoing is CCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE COCEDU	andonment Notices shall be final inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8"CSG.SI 0+/-1,300'. 55'-1,245'(5-1/2"CSG.S' 5'-250'(T/SALT,13-3/8"C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE PER OCD RULE 19.15. True and correct. Electronic Submission f For COG (formitted to AFMSS for pr SYLER Ubmission) THIS SPACE F(1. Approval of this notice doe itable title to those rights in th ct operations thereon. J.S.C. Section 1212, make it a	led only after al 6,600'-6,425 /OC X TAG (HOE, T/DLWF TUB); WOC) SG SHOE); V ON STEEL E CLOSED-L(17. 2257601 verifin 27605 v	I requirements, includ (T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC TAG CMT. PUL WOC X TAG CMT. PLATE TO CSGS OOP SYSTEM W C, sent to the C JAMES AMOS on Title AGENT Date 08/19/2 AL OR STATE Office CM	willfully to m	new interval, a Form 316 n, have been completed, SEE ATTACHE CONDITIONS LL DRY HOLE MARI TANK AND HAUL C SE SE ake to any department or	50-4 shall be filed once and the operator has ED FOR OF APPROVA KER. ONTENTS TO DI JOJY MATION PROCEDUR ATTACHED agency of the United	
determined that the site 1) SET 5-1/2" CIBI 2) PUMP 25 SXS (3) PUMP 25 SXS (4) PUMP 70 SXS (5) CUT X PULL 5- 6) PUMP 40 SXS (7) PUMP 75 SXS (8) MIX X CIRC. TO 9) DIG OUT X CUT DURING THIS PR THE REQUIRED D 14. I hereby certify that the Name (Printed/Typed) Signature 	leted. Final Ab e is ready for final P @ 6,600'; CMT. @ 6,0 CMT. @ 4,5 CMT. @ 2,7 1/2" CSG. @ CMT. @ 1,3 CMT. @ 405 D SURF. 25 T OFF WELL COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I he foregoing is CCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE DISPOSAL, I COCEDURE COCEDU	andonment Notices shall be fi nal inspection.) PUMP 30 SXS.CMT. @ 76'-5,916'(DV TOOL); W 70'-4,430'(MID-PLUG). 95'-2,300'(9-5/8''CSG.SI 0+/-1,300'. 55'-1,245'(5-1/2''CSG.S' 5'-250'(T/SALT,13-3/8''C SXS.CMT. @ 63'-3'. LHEAD 3' B.G.L.; WELD WE PLAN TO USE THE PER OCD RULE 19.15. True and correct. Electronic Submission # For COG 6 committed to AFMSS for pr EYLER ubmission) THIS SPACE F(Approval of this notice doe itable title to those rights in the ct operations thereon. J.S.C. Section 1212, make it a tatements or representations a	led only after al 6,600'-6,425 /OC X TAG (HOE, T/DLWF TUB); WOC) SG SHOE); V ON STEEL E CLOSED-L(17. 2257601 verifin 27605 v	I requirements, includ (T/B.S.); CIRC.V CMT. PLUG. R,B/SALT); WOC TAG CMT. PUL WOC X TAG CMT. PLATE TO CSGS OOP SYSTEM W C, sent to the C JAMES AMOS on Title AGENT Date 08/19/2 AL OR STATE Office CM	willfully to m	new interval, a Form 316 n, have been completed, SEE ATTACHE CONDITIONS LL DRY HOLE MARI TANK AND HAUL C SE SE ake to any department or	50-4 shall be filed once and the operator has ED FOR OF APPROVA KER. ONTENTS TO DI JOJY MATION PROCEDUR ATTACHED agency of the United	



Hambone Fee Com #1H API# 30-015-38980 CONC SPUD RR Eddy County, NM / Section 5, T-26S, R-29E DRILLING Concho LAST REVISED SHL: 660' FSL & 330' FWL 8/4/2014 TLM BHL: 660' FSL & 330' FEL KB 18.0 GL 2906 Hole CIRC. 25 5×5.CMT. @ 63-3. 2 17-1/2" 300 13-3/8" 48# H-40 STC TOC (@) Surface Pump 75 sxs. cmi @ 405'-250'-1746 Pump 45 5×5.cmi. @ 1355'-1245'-TAG TOC @ 1,320' CUT X PULL 51/2" CSG.@ 1300! 2,745 12-1/4''9-5/8" 36# J-55 STC TOC @ Surface PUMP 705×5. CMTCP 2795-2300-TAG Pump 25 5×5 cmTC 4570'-4430! Perts/Frac Stadi 6950, 7021, 7092, 7163, 7234 7305, 7377, 7448, 7519, 7590 7651, 7732, 7803, 7874, 2945 8016, 8088, 8159, 8230, 8301 8372, 8443,8514,8585, 8656 8727, 8795, 8870, 8941, 9012 9083. 9154, 9225, 9296, 9367 9438, 9509, 9580, 9652, 9723 9794, 9865, 9936, 10007, 10078 10149, 10220, 10291, 103.63, 10434 5.5" **DVT/ECP** 5.996 10505, 10576, 10647, 10718, 10789 10860, 10931, 11002; 11073, 11145 11216, 11287, 1135 Pump 25 5×5.cmT. @ 6076-5916'-TAG Pump 30 5x5 CMT. @ 6600'-6425' SET 51/2" CD3P @ 6600'. EOC @ 7.569 5-1/2" 17# P-110 LTC KOP = 6,675' TOC @ 1.320" 7-7/8" TD = 11.715' MDCement Plug Csg = 11.715' MD TVD = 7,200' **Pilot Hole** 9,150 DAE 08/19/14

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon. (9# brine is not mud)

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. **Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Interim Reclamation Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses.

Interim reclamation consists of minimizing the footprint of disturbance by reclaiming all portions of the well site not needed for production operations. The portions of the cleared well site not needed for operational and safety purposes are recontoured to a final or intermediate contour that blends with the surrounding topography as much as possible. Sufficient level area remains for setup of a workover rig and to park equipment. Topsoil is respread over areas not needed for all-weather operations. Production facilities should be clustered to maximize the opportunity for interim reclamation. In order to inspect and operate the well or complete workover operations, it may be necessary to drive, park, and operate on restored, interim vegetation within the previously disturbed area. This is generally acceptable provided damage is repaired and reclaimed following use.

To reduce final reclamation costs; maintain healthy, biologically active topsoil; and to minimize habitat, visual, and forage loss during the life of the well, all salvaged topsoil should be spread over the area of interim reclamation, rather than stockpiled.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). Interim reclamation is to be completed within 6 months of well completion.
- 3. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with interim reclamation as per approved APD or Sundry Notice. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the reinoval of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 4. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 5. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist

Solomon Hughes Natural Resource Specialist 575-234-5951

Douglas Hoag Civil Engineering Technician 575-234-5979