• • • Form 3160-5		OCD Artesia			
(August 2007)	DEPARTMENT OF THE	UNITED STATES ARTMENT OF THE INTERIOR		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010	
	BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			5. Lease Serial No. NMNM104661	
Do n aband				ee or Tribe Name	
Co. SUBM	<i>C</i> SUBMIT IN TRIPLICATE - Other instructions on reverse side.			greement, Name and/or No. 2	
1. Type of Well Dil Well 🛛 Gas W	1. Type of Well □ Oil Well ☑ Oil Well ☑ Other			8. Well Name and No. TRINITY 20 FEDERAL COM 2	
2. Name of Operator CIMAREX ENERGY	2. Name of Operator Contact: TERRI STATHEM CIMAREX ENERGY COMPANY OF CO-Mail: tstathem@cimarex.com			9. API Well No. 30-015-34500-00-S2	
3a. Address 600 NORTH MARIE MIDLAND, TX 7970	NFELD STREET SUITE 600	3b. Phone No. (include area code Ph: 432-620-1936			
4. Location of Well (Foot	tage, Sec., T., R., M., or Survey Descriptio	n)	11. County or Pari	sh, and State	
Sec 20 T25S R26E	NWSW 1980FSL 660FWL		EDDY COUM	ITY, NM	
12. CHE	CK APPROPRIATE BOX(ES) T	O INDICATE NATURE OF	NOTICE, REPORT, OR OTI	IER DATA	
TYPE OF SUBMISS	SION	TYPE OF ACTION			
□ Notice of Intent	Acidize	Deepen	Production (Start/Resume) Replacemention		
🛛 Subsequent Report	Alter CasingCasing Repair	Fracture Treat New Construction	Reclamation Recomplete	□ Well Integrity □ Other	
Final Abandonment	Notice Change Plans	Plug and Abandon	Temporarily Abandon		
	Convert to Injection mpleted Operation (clearly state all pertine		UWater Disposal		
determined that the site is Cimarex has plugge	ed. Final Abandonment Notices shall be fiss ready for final inspection.) d back to 9949'. Abandoning the I olfcamp (9164-9930') as indicated	Morrow (ABANDONED PERF			
to the casing and ce 13-3/8", 48#, H-40 s	viewed the initial completion paper menting information. Below is the et @ 214'. 220 sx circ @ 2681'. 775 sx circ	rwork and has found multiple of correct casing/cement info:	NM OIL C	ONSERVATION	
7", 26#, N80 set @ 1	@ 12310' 240 sx - TOC @ 2400' TS @ 12310' 240 sx - TOC 10950'	ten ula	ARTESIA DISTRICT NOV 17 2014		
			NMOCD RECEIVED		
				CEIVED	
14. I hereby certify that the	For CIMAREX EN	#276791 verified by the BLM We ERGY COMPANY OF CO, sent rocessing by JAMES AMOS on	to the Carlsbad		
Name(Printed/Typed)			DINATOR REGULATORY CO	MPLIA	
Signature	Electronic Submission)	Date 11/07/2	2014		
	THIS SPACE F	OR FEDERAL OR STATE	OFFICE USE	· · · · ·	
Approved By ACC			AMOS SORY PET	Date 11/12/201	
certify that the applicant holds	, are attached. Approval of this notice doe legal or equitable title to those rights in th ant to conduct operations thereon.				
Title 18 U.S.C. Section 1001 a States any false, fictitious or	and Title 43 U.S.C. Section 1212, make it a fraudulent statements or representations a	a crime for any person knowingly and s to any matter within its jurisdiction	d willfully to make to any departmen	t or agency of the United	
** B	LM REVISED ** BLM REVISE		WI REVISED ** BLM REVIS	DEN	
) ·	
, · · ·				· .	

Trinity 20 Fed 2 Recomplete to Wolfcamp 30015-34500

<u>CIBP information and well history in order to correct previously submitted IP paperwork:</u> 09/2006 – CIBP @ 11921'. CIBP @ 11690' w/ 2 sx cmt on top. TOC @ 11660'. CIBP @ 11540'. Perfs: Morrow @ 11446-12112'.

Casing / Cement information:

13-3/8", 48#, H-40 set @ 214'. 220 sx circ 9-5/8", 40#, J-55 set @ 2681'. 775 sx circ 7", 26#, N80 set @ 10001'. 550 sx - TOC @ 2400' TS 4-1/2", 11.6#, P110 @ 12310' 240 sx - TOC 10950'

Abandon Morrow & Recomplete to Wolfcamp:

6/15/13 SICP 2000#. Mill on spear to 9660'. Spear fell down hole. RIH w/ tbg to tag @ 10,842' (42' below chemical cut)

6/18/13 SICP 2000#. Perforate 2 holes @ 9951'.

6/22/13 SICP 1650#. RIH w/ 4-1/2" CICR & set @ 10,700'.

6/26/13 SICP 1450#. Perforate csg @ 10,696'.

6/27/13 SICP 1600#. Perforate csg @ 10,432'.

6/29/13 SICP 1650#. Pump 44 sx class H cmt to squeeze perfs. Tag TOC @ 10,096'

7/2/13 SICP 700#, SITP 2700#. Cut csg @ 10,051'.

7/9/13 SICP 1750#. Try to establish rate thru cut @ 10,051', but couldn't get inj rate. Discussed w/ BLM. Decision made to run mech cutter to cut liner @ 10,000'.

7/11/13 SICP 1700#. Cut liner @ 10,000'. Jar on liner, could not get any movement.

7/13/13 SICP 1700#. RIH w/ 4-1/2" CICR & set @ 9,980'. SDFW.

7/16/13 SICP 2400#. Pump 25 sx class H cmt thru retainer @ 9,980' and out cut in liner @ 10,000'.

7/19/13 SICP 1500#. Tag cmt @ 9,860'. Drill out cmt down to CICR @ 9,980'. No break in cmt through perf hole @ 9,951'.

7/23/13 SICP 1400#. Discuss pressures w/ blm and they wanted to do a pressure up test on perf @ 9,951'. Pressure test at 700 psi for 30 mins, no leak off. BLM said we did not need to drill up CICR. Load 30' dump bailer and dump 30' class H cmt on top of CICR.

7/24/13 SICP 1400#. Tag TOC w/ wireline @ correlated depth of 9949'.

7/25/13 SICP 1400#. Talked to BLM & they wanted to see a tag of TOC w/ tubing. RIH to tag cmt w/ bit @ 9949'. BLM (Kent Caffall) witnessed tag.

7/29/13 MIRU. Install WH. Test to 3000# ok.

7/30/13 0 psi on csg & tbg. Release pkr & RBP. RIH w/ RBP & set @ 9600'. Set pkr & press test RBP to 3000# ok. Release prk & POOH. SWI.

08/01/13 Press test csg to 300 psi. RIH w/ pkr to 6502' – 100' below DV tool. Press up to 4000#. Held ok. Set pkr @ 6406'. Test csg to 4000#. Found leak @ 6504-6536'. RIH and latch on to RBP @ 9600'. SDFN.

Trinity 20 Fed 2 Recomplete to Wolfcamp 30015-34500 Page 2

08/02/13 POH w/ pkr & RBP. SDFN.

08/03/13 RIH w/ 7" composite plug and set @ 9592'. SWI. WO engineering evalution.

11/02/13 MIRU. Flowback well.

11/05/13 SICP 2000#. MIRU. POOH w/ tbg. SWI.

11/06/13 SICP 1300#. Finish POOH w/ tbg.

11/07/13 SICP 1350#. RU WL. RIH w/ 6" RGJB to tag composite plug @ 9592'. POH and RIH w/ 7" 10K composite plug & set 2" above previous plug. POOH. RD WL. SI.

11/08/13 SICP 300#. RIH w/ 7" pkr & set @ 6532'. Test csg & plug to 5800# for 30 mins. OK. Test csg above pkr to 5000# for 30 mins. OK. Pull pkr up hole to 6532'.

11/09/13 0# CSIP. MIRU cementers. Mix & pump 15 sx Class C cmt. Set pkr. WOC over weekend.

11/11/13 Release pkr & POOH. Tag cmt @ 6510'. RU swivel & stripper head, press test cmt pior to drill to 4000#. No leak off. Drill cmt from 6510' to 6532' cont to 6588'.

11/13/13 POOH w/ tbg. No obstructions. Ran shoe mill shoe past 6520'. POOH & LD.

11/14/13 Caliper log shows DV tool @ 6469', leak @ 6514. Set csg patch @ 6524-6464'. POOH.

11/15/13 POOH. Test csg & patch to 5800# for 30 mins. Ok. Charted. RIH w/ tbg.

11/21/13 Tag composite plug @ 9590'. DO. Tag 2nd plug @ 9592'. DO down to 9949' Circ sweep. Work bit thru liner top until clean. RD. SWI.

01/07/14 MIRU. SICP 1400#. RIH w/ WL tools to 9624'. SWI.

01/08/14 could not get passed 9624'. SWI.

01/09/14 SICP 1200#. RIH & tag @ 9624'. Work thru debris to 9932'. Work thru from to to bottom w/ no restrictions. RD.

01/11/14 MIRU and perf Wolfcamp @ 9629-9930', 72 holes. WO frac.

04/03/14 MIRU frac trucks.

04/05/14 Perf @ 9164-9166'. Frac w/ 984826 gals total fluid, 860780# sand.

04/06/14 Flowback well.

04/10/14 DO composite plugs & CO to PBTD @ 9949'.

04/13/14 RIH & set pkr @ 9132'. POOH.

04/15/14 RIH w/ tbg & GL and set @ 9132¹. GLV @ 1719, 3217, 4489, 5467, 6281, 6966, 7685, 8437, 9090'. Flowback well. Turn well over to production.