
Submit 1 Copy To Appropriate District	State of New Me	xico		Form C-103		
Office <u>a</u> <u>District 1</u> – (575) 393-6161	Energy, Minerals and Natur	ral Resources		Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-005-63679			
811 S. First St., Artesia, NM 88210	t., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE			
District IV - (505) 476-3460	ct IV - (505) 476-3460 Santa Fe, NM 8/505		6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505			VA-2030			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Barracuda ABV State	Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			8. Well Number			
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			1			
2. Name of Operator			9. OGRID Number			
Yates Petroleum Corporation			025575			
3. Address of Operator 105 South Fourth Street, Artesia, NM 88210			10. Pool name or Wildcat Foor Ranch; San Andres (Gas)			
4. Well Location	NW 88210		Tool Railen, San Andre	-S (Gas)		
Unit Letter H:	1680 feet from the North	line and	feet from the	<u>East</u> line		
Section 5	Township 10S Rar	nge 27E	NMPM Chaves	County		
	11. Elevation (Show whether DR,		117	A Prince		
The second secon	3934'	GR	The Control of the Co	Trans.		
12 (11-	A	-4 CNI-4:	D O4l D - 4-	•		
12. Check	Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data	l		
	NTENTION TO:	SUB	SEQUENT REPOR			
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON	REMEDIAL WOR		ERING CASING 🔲		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		ID A		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	I JOB 📙			
DOWNHOLE COMMINGLE						
OTHER:		OTHER:				
	oleted operations. (Cléarly state all p					
	ork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Cor	npletions: Attach wellbo	re diagram of		
proposed completion or rec	completion.					
Yates Petroleum Corporation plans	to plug and abandon this well as foll-	ows:				
•						
	ed. No casing recovery will be attem			ipment.		
	nent plug from 2600'-2700'. This put it 35' of cement. This puts a plug of					
	nent plug from 1284'-1384'. This pu			oe. WOC and tag		
plug.			•	_		
•	x Class "C" cement plug from 380'-4	480'. This puts a 10	00' plug across surface ca	ising shoe, inside and		
outside casing. WOC and tag plug.	Class "C" cement plug from 60' up	to surface				
	weld dry hole marker and clean locati		ns.			
- Im-F			and the second of the second o	OIL CONSERVATION		
Wellbore schematics attached		Approved for plugging	is retained pending receipt	ARTESIA DISTRICT		
CONDITIONS OF APPROVAL ATTAC	HED	of C-103 (Subsequer	t Report of Well Plugging)	NOV 26 2014		
American Court III	Rig Release Da	which may be found ite: Forms, www.cmnrd.s	at OCD Web Page under			
Approval Granted providing wor	rk is	Totals, www.clantus	internal dayoed.	RECEIVED		
Completed by 11-26-20)/5			*/FCF1AFD		
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief.			
4	, 1		•			
SIGNATURE ()	TITLE Regu	ılatory Reporting Sı	: upervisor DATE <u>No</u>	wember 25, 2014		
SIGIMI ONE TO THE	THE TRUE	natory Reporting of	<u> </u>	<u>vemoet 25, 2014</u>		
Type or print name Tina Hu	erta E-mail address: tin	nah@yatespetroleun	n.com PHONE:	575-748-4168		
For State Use Only	`	~~~ C		•		
APPROVED BY:	ade title 1)15	THUDE	DATE /	1/26/2014		
Conditions of Approval (if any):	See Attached	1000'		//		
	> Jee 17/140/180		}	· 		



PAM DEPTH SET STAC 430 TAC 1,334 TAC 6,590
DEPTH SET 574C 430' 74C 1,334'
TAC 1,334"
TIC 1,334'
1726,590
7706,590
100 SACKS
(100 3445)
Surface
•
Ima coales
1700 SACKS
1700 sacks surface
s p S
: 1,436 \
= 2,636
: 4892
: 5,5'69'
: 6,108'
6,226 6,376
: 6.41h
5/05
104
KS, CMTD
12/04 Jul

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:_	YATES	Pet.			
		Barracuda	ABV	51ete	#
API #:	30-0	05-6367	9		

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 11/26/2014

APPROVED BY: AD

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement,
 whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
 plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).