
		NM OIL CON				
Form 3160-5 (March 2012) DFF	UNITED STATES PARTMENT OF THE INTE			FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014		
BUR	EMENT		5. Lease Serial No. C. 058481			
SUNDRY N	IOTICES AND REPORTS	S ON WEIRESCEI	IVED	If Indian, Allottee o	-	
Do not use this f	orm for proposals to dr Use Form 3160-3 (APD)	ill or to re-enter	an (
				If Unit of CA/Agree	ement, Name and/or No.	
1. Type of Well	T IN TRIPLICATE – Other instru	ictions on page 2.			,	
Oil Well Gas Well Other				8. Well Name and No. WLH Gas Unit #52		
2. Name of Operator EnerVest Operating, LLC				9. API Well No. 30-015-37020		
3a. Address 3b. Phone No. (include area cod 1001 Fannin, Suite 800, Houston, TX 77002 743.970.1847				10. Field and Pool or Exploratory Area Loco Hills;Qu-GB-SA		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2620' FNL & 1360' FWL (Unit Letter F), Sec. 11, T18S, R29E				11. County or Parish, State Eddy County, NM		
12. CHEC	K THE APPROPRIATE BOX(ES)) TO INDICATE NAT	URE OF NOTICE	, REPORT OR OTHI	ER DATA	
TYPE OF SUBMISSION TYPE OF AC)N		
Notice of Intent	Acidize	Deepen Fracture Treat	Reclan		Water Shut-Off	far
Subsequent Report	Casing Repair	New Construction Plug and Abandon	Recom	plete f [#] ratily Abandon	Pother <u>prep</u>	105
Final Abandonment Notice	Convert to Injection	Plug Back	Water	Disposal	reque	st_
 following completion of the involv testing has been completed. Final a determined that the site is ready for 1. Clean Location & test anchors. Sh 2. MiRU workover rig. 3. If necessary, kill well with 2% KCI 4. POOH w/ rods and pump. Lay do 	Abandonment Notices must be filed final inspection.) noot fluid level & record pressure . Keep kill truck on location as n	d only after all requiren	nents, including re	clamation, have been OWN J Peldeoor	completed and the operato	r has
 5. NDWH, NUBOP and test. 6. PU additional tbg jnts & tag bottor 					VITNESS	
 POOH scanning and laying down MIRU wireline. RIH w/ 5-1/2" CIBP & set @ 2,578 Bail 20' cement on top of plug. RDMO wireline. Inform OCD and/or BLM of inten 13. Load casing w/ 2% KCL & test to test. Chart & sign test. If test fails ca 	tbg. 8' (50' above top perf @ 2,628'). ht to demonstrate mechanical int o 600 psi surface pressure. Hold Il engineer to discuss.	conditional contemporary and pressure & monitor		ROVAL.	UG BAC	
14. Clean location, RDMO. Cur Appropriate for	rent Wellbore schematic attach	on ONLY			· ·	
Approved for BLM is NOT			us.		JECT TO LIKE ROVAL BY STA	TE
 14. 1 hereby certify that the foregoing is tr Jeanie McMillan 		Title Sr. Regulatory Analyst			1	
Signature Spanie To	rMillan	Date 4	5/28/14	L A	PPROVED	
	THIS SPACE FOR	FEDERAL OR	STATE OFFI	CEUSE		7
Approved by	Approval of this notice does not w	Title			OCT 3 1 2014	
that the applicant holds legal or equitable ti entitle the applicant to conduct operations t	itle to those rights in the subject lease thereon.	which would Office			U OF LAND MANAGEN	
Title 18 U.S.C. Section 1001 and Title 43 fictitious or fraudulent statements or repre			ly and willfully to i	nake to any department	ndragenly braicium als sid	es any false,



CURRENT WBD:



3

Conditions of Approval

EnerVest Operating, LLC WLH Gas Unit - 52, API 3001537020 T18S-R29E, Sec 11, 2620FNL & 1360FWL October 31, 2014

An inactive/shut-in well bore is a non-producing completion that is capable of production in **paying quantities** or of service use.

Temporary abandonment status will be granted **only after justification of impending "beneficial use",** the well has been plugged back per Onshore Order #2.III.G. and N.M.O.C.D. plugging guidelines, and has passed a mechanical integrity test.

Consider the beneficial use prospects and the wellbore integrity of this well. Submit your plan for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies).

As the current operator you are required to: **Prove the production casing integrity from no** more than 100 feet above the perforations or open hole with a documented minimum pressure test of 500psig for 30 minutes.

Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 25 to 85 per cent of its full range. Greater than 10% pressure leakoff will be viewed as a failed MIT. Verify all annular casing vents are plumbed to surface and those valves open to the surface during this pressure test. Pressure leakoff will be evaluated site specifically and may restrict continued operation approval. Twenty four hours before the test contact BLM to witness; 575-200-7902 Eddy Co., if there is no response, 575-361-2822 as work begins. Procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.

Should the mechanical integrity test fail or <u>not be conducted</u> submit a procedure to plug and abandon the well for BLM approval on or before 01/28/2015.

A legitimate request is necessary for extension of that date.

References: 43 CFR 3162.1(a), 43 CFR 3162.3-2, 43 CFR 3162.3-4, 43 CFR 3162.4-1, Onshore Oil and Gas Order #1.X., & Onshore Oil and Gas Order #2.III.G.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html § 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.