NM OIL CONSERVATION

ARTESIA DISTRICT

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

JAN **06** 2015 Be

Form C-141 Revised August 8, 2011

Support E Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action											
NAB1500736485						OPERA	ror	🛛 Ini	tial Report	\boxtimes	Final Report
Name of Company: Devon Energy Production Co LP						Contact: Martin Jimenez, Completions Foreman					
(6137)				V	15			•			
							Telephone No. 575- 513-5819				
Facility Nar	ne: Cotto	n Draw 10	Fed Com	3Н	Facility Type : Well location						
Surface Owner: BLM Mineral Owner:						BLM API No. 30-015-42126					
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/West Line Coun			
A	10	25S	31Ē	200	ז	North	1200	East	Eddy		
									_ <u>l</u>]
Latitude: Longitude:											
NATURE OF RELEASE											
Type of Release: Tank Fire							Volume of Release: 0 Volume Recovered: NA				
Source of Release: Frac Tanks							Date and Hour of Occurrence Date and Hour of Discovery				
							12/20/2014, 10:00 A.M. 12/20/2014, 10:00 A.M.				
Was Immediate Notice Given?							If YES, To Whom?				
					quired	OCD-Mike Bratcher BLM-Jim Amos					
By Whom? Email from Denise Menoud / Devon Artesia							Date and Hour: 12/22/2014, 9:54 A.M.				
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.				
🗌 Yes 🖾 No											
If a Watercourse was Impacted, Describe Fully.* N/A											
Describe Cause of Problem and Remedial Action Taken.*											
The pulling unit crew was drilling out the last frac plug when the swivel broke down, which took 1 hour to replace. The crew resumed operations by								ons by			

The pulling unit crew was drilling out the last frac plug when the swivel broke down, which took 1 hour to replace. The crew resumed operations by breaking circulation and continued to drill out the plug. The Devon consultant noticed Frac Tank #1 on the far south, which was being flowed into, had flames coming from the top of the tank. This caused the fire to spread to the other two tanks. They immediately shut down operations and secured location, accounting for everyone. The Loving Fire Department was called and they were able to extinguish the fires. No injuries or spills occurred.

Describe Area Affected and Cleanup Action Taken.*

Tanks have been cleared from location. No further actions required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: A. Menserd	OIL CONSERVATION DIVISION					
Printed Name: Denise Menoud	Approved by Environmental Specialist:					
Title: Field Admin Support	Approval Date: 1115 Expiration Date: MIA					
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval:					
Date: 1/5/2015 Phone: 575-746-5544	I-INAC I					
Attach Additional Sheets If Necessary	3RP- 3714					