

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

X Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No.	(432)556-8730
Facility Name	Poker Lake Unit #108 Flowline	Facility Type	E&P
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	25	24S	30E					Eddy

Latitude 32.18713° North

Longitude 103.83280° West

NATURE OF RELEASE

Type of Release	Produced water and crude oil	Volume of Release	5 bbls of produced water and 5 bbls of crude oil	Volume Recovered	0
Source of Release	2 7/8" flow line	Date and Hour of Occurrence	8/17/11, Hour unknown	Date and Hour of Discovery	8/17/11, 1:30 a.m.
Was Immediate Notice Given?	Yes No X Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					

RECEIVED

JAN 04 2012



NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.* A flow line near well PLU-108 developed a leak. The well was shut in until daylight hours. 3 sections of pipe were replaced the next morning.

Describe Area Affected and Cleanup Action Taken.* The release affected an area of pastureland measuring approximately seven hundred square feet (700 ft²). During the site assessment, it was noted that the spill initially reported as the Poker Lake Unit #108 was actually on a flow line from Poker Lake Unit #84. It was also noted that there were at least twelve (12) clamps on the four (4) flow lines that run along the side of the lease road to/from the following pumping wells: Poker Lake Units #84, #105, #111, and #118. The flow path of the August 17, 2011, release noted as Poker Lake Unit #108 mingled with historical releases from these flowlines. Since the area affected by the August 17, 2011, release is indistinguishable from that affected by the historical releases, the releases were remediated simultaneously, in accordance with NMOCD and BLM guidelines. Please reference the attached *Remediation Summary & Risk-Based Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Tony Savoie	Approval Date: 1/16/15	Expiration Date: NA
Title: Waste Mgmt. & Remediation Specialist	Conditions of Approval: Final	
E-mail Address: TASavoie@BassPet.com		
Date: 12/29/2011	Phone: (432)556-8730	

2RP-872