District 1 1625 N. French Dr., Hobbs, NM 882 District II

State of New Mexico VED State of New Minerals and Natural Resources

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

District III
1000 Rio Brazos Road, Aztec, NM 87410

Oil Conservation Division 1220 S. St. Francis Dr., Santa Fe, NM26D ARTESIA 1220 South St. Francis Dr.

Release Notification and Corrective Action

			ICI	case I willing	cauo.	n and Co	Ji i celive A	CHOII				
			PER	ATOR			Initial	Report				
Name of Co		BOPCO, L		Contact Tony Savoie								
Address 522 W. Mermod, Suite 704, Carlsbad, NM 88220 Telephone No. 432-556-8730												
Facility Name Poker Lake Unit 341H 2RP- 1926 Facility Type Exploration and Production												
Surface Ow	vner Fede	ral	wner	Federal Lease No. 30-015-39486					-39486			
LOCATION OF RELEASE												
Unit Letter D							Feet from the 1110	East/West West	t Line	County Eddy		
Latitude 32.208112° North Longitude 103.856698° West												
NATURE OF RELEASE												
Type of Rele	ase Produc	ed water		Volume of Release >50 bbls Vo			olume Recovered: none					
Source of Release Frac tanks							8/24/13 approximately 5:00 a.m.			Date and Hour of Discovery: By Q.T. 9/6/13		
Was Immediate Notice Given? ☐ Yes ☑ No ☐ Not Required						If YES, To Whom? BOPCO notified the NMOCD and BLM immediately upon their discovery of the spill on 9/10/13.						
By Whom? Tony Savoie						Date and Hour 9/11/13 10:00 a.m.						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken:* A produced water treatment process was set up on the PLU-341 pad for the frac job on the PLU-Big Sinks 15-24-30 USA #1H, The frac tanks were placed on plastic lined containment. The tanks overflowed undetected and breached the containment on the back side of the frac tanks, the produced water traveled out onto the well pad and pasture. The cause of the overflow was corrected when it was discovered. Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 19,400 sq. ft. of well pad and approximately 18,250 sq. ft. of pasture. Soil samples were collected on 9/11/13 to determine the impact area on the pad and pasture area and the vertical extent in the pasture. Quality Trucking will be performing the dirt work, BOPCO and a project												
manager will be overseeing the remediation activities. The remediation will be done in accordance to the NMOCD and BLM guidelines for the remediation of leaks and spills.												
Remediation a	activities co	nducted at the	PLU #34	1H Remediation	Site me	t the objective	es set forth by the	NMOCD a	and BLI	M. Soil san	ples collected from	
Remediation activities conducted at the PLU #341H Remediation Site met the objectives set forth by the NMOCD and BLM. Soil samples collected from the floor and sidewalls of the excavation were analyzed by an NMOCD-approved laboratory which determined concentrations of BTEX, TPH and Chloride were less than NMOCD Regulatory Standards. Between September 23, 2013, and January 14, 2014, approximately 6,040 cy of impacted soil was excavated and transported to an NMOCD-approved disposal facility. Please reference the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remediation activities.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.												
Signature.	1 Bry	2a		OIL CONSERVATION DIVISION								
Printed Name:	Tony Savo	ie		A	Approved by District Supervisor:							
Title: Waste M	Mgmt. & Re	mediation Spo		Approval Date: 10/27/14 Expiration Date: NA								
E-mail Addres	s: TASavoi	e@BassPet.co	c	onditions of A	Approval:	$\overline{}$	0		·			
Date: 12/6/201	11		Pho	one: (432)556-873	80_			Tina	$\mathcal{X} \mid$			