

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

MAR 6 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1506838749

Name of Company: OXY USA Inc.		Contact: Chris Jones	
Address: 102 S. Main St. Carlsbad, NM 88220		Telephone No.: 575-628-4121	
Facility Name: Pure Gold A Federal #8		Facility Type: Battery	
Surface Owner: Federal		Mineral Owner:	API No.: 30-015-35296


LOCATION OF RELEASE

Unit Letter F	Section 21	Township 23S	Range 31E	Feet from the 1860'	North/South Line North	Feet from the 1860'	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------

Latitude **32.292065195 N** Longitude **-103.784888876 W**

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 7 bbls Oil	Volume Recovered: 1.5 bbls
Source of Release: LACT Unit Leak	Date and Hour of Occurrence 2/27/2015	Date and Hour of Discovery 2/27/2015 @ 11:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The transfer line to the LACT unit froze causing a release of 7 barrels of oil on the location. The facility was shut in and the line was replaced. A vac truck recovered 1.5 barrels of fluid. Talon/LPE was contracted to perform an initial site assessment and soil sampling.		
Describe Area Affected and Cleanup Action Taken.* The area affected is in front of the LACT unit measuring approximately 60-feet long and 30-feet wide. All fluids remained on location.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: Chris Jones <small>Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US; Date: 2015.03.06 08:18:30 -06'00'</small>	OIL CONSERVATION DIVISION	
	Approved by Environmental Specialist: 	
Printed Name: Chris Jones	Approval Date: 3/9/15	Expiration Date: N/A
Title: HES Specialist	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
E-mail Address: Christopher.Jones@oxy.com	Attached <input type="checkbox"/>	
Date: 3/5/2015	Phone: 575-628-4121	

* Attach Additional Sheets If Necessary

LATER THAN: **4/9/15**

2PP-2869