				•
BUNDRY I	UNITED STATES PARTMENT OF THE INT JREAU OF LAND MANAGE NOTICES AND REPORT s form for proposals to dr I. Use form 3160-3 (APD)	TERIOR EMENT MAR	2 3 2015 5. Lease Serial No. NMNM10466	
SUBMIT IN TRI	PLICATE - Other instruction	ons on reverse side.	7. If Unit or CA/Ag NMNM120212	reement, Name and/or No.
1. Type of Well Oil Well 🛛 Gas Well - 🗋 Oth		8. Well Name and No. TRINITY 20 FEDERAL COM 2		
2. Name of Operator CIMAREX ENERGY COMPAN	9. API Well No. 30-015-34500	9. API Well No. 30-015-34500-00-S2		
3a. Address 600 NORTH MARIENFELD S MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432-620-1936	10. Field and Pool,	10. Field and Pool, or Exploratory SAGE DRAW	
4. Location of Well <i>(Footage, Sec., T.</i> Sec 20 T25S R26E NWSW 19			11. County or Parish, and State EDDY COUNTY, NM	
12. CHECK APPF	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF N	NOTICE, REPORT, OR OTH	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
 Notice of Intent Subsequent Report 	 Acidize Alter Casing 	 Deepen Fracture Treat 	 Production (Start/Resume) Reclamation 	□ Water Shut-Off □ Well Integrity
Final Abandonment Notice	 Casing Repair Change Plans Convert to Injection 	 New Construction Plug and Abandon Plug Back 	 Recomplete Temporarily Abandon Water Disposal 	🗖 Other
 Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for find Cimarex has plugged back to completing in the Wolfcamp (S Cimarex has also reviewed the to the casing and cementing in 13-3/8", 48#, H-40 set @ 214' 9-5/8", 40#, J-55 set @ 2681', 7", 26#, N80 set @ 10001'. 5 4-1/2", 11.6#, P110 @ 12310' 	Illy or recomplete horizontally, give k will be performed or provide the operations. If the operation result andonment Notices shall be filed and inspection.) 9949'. Abandoning the Mor 0164-9930') as indicated on the initial completion paperwo offormation. Below is the col . 220 sx circ 775 sx circ 50 sx - TOC @ 2400' TS	ve subsurface locations and measu e Bond No. on file with BLM/BIA ts in a multiple completion or reco- only after all requirements, includi rrow (ABANDONED PERFS the attached well history. ork and has found multiple e	red and true vertical depths of all per . Required subsequent reports shall mpletion in a new interval, a Form 3 ing reclamation, have been complete 5 - 11446-12112') and	tinent markers and zones. be filed within 30 days (160-4 shall be filed once d, and the operator has SERVATION ISTRICT
14. Thereby certify that the foregoing is				VED
Constant Con	For CIMAREX ENER(ommitted to AFMSS for proce	6791 verified by the BLM Wel GY COMPANY OF CO, sent to essing by JAMES AMOS on 1 Title COORD	o the Carlsbad	MPLIA
Signature (Electronic S	Submission)	Date 11/07/20	014	
· · · · · · · · · · · · · · · · · · ·	THIS SPACE FOR	R FEDERAL OR STATE	·····	
Approved By ACCEPTED onditions of approval, if any, are attached. Approval of this notice does not warrant or ertify that the applicant holds legal or equitable title to those rights in the subject lease			JAMES A AMOS TitleSUPERVISORY PET Date 11/12/2014	
which would entitle the applicant to condu- Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a cri			or agency of the United
** BLM REV	ISED ** BLM REVISED *	** BLM REVISED ** BLN	I REVISED ** BLM REVIS	ED **

Trinity 20 Fed 2 Recomplete to Wolfcamp 30015-34500

<u>CIBP information and well history in order to correct previously submitted IP paperwork:</u> 09/2006 – CIBP @ 11921'. CIBP @ 11690' w/ 2 sx cmt on top. TOC @ 11660'. CIBP @ 11540'. Perfs: Morrow @ 11446-12112'.

Casing / Cement information:

13-3/8", 48#, H-40 set @ 214'. 220 sx circ 9-5/8", 40#, J-55 set @ 2681'. 775 sx circ 7", 26#, N80 set @ 10001'. 550 sx - TOC @ 2400' TS 4-1/2", 11.6#, P110 @ 12310' 240 sx - TOC 10950'

Abandon Morrow & Recomplete to Wolfcamp:

6/15/13 SICP 2000#. Mill on spear to 9660'. Spear fell down hole. RIH w/ tbg to tag @ 10,842' (42' below chemical cut)

6/18/13 SICP 2000#. Perforate 2 holes @ 9951'.

6/22/13 SICP 1650#. RIH w/ 4-1/2" CICR & set @ 10,700'.

6/26/13 SICP 1450#. Perforate csg @ 10,696'.

6/27/13 SICP 1600#. Perforate csg @ 10,432'.

6/29/13 SICP 1650#. Pump 44 sx class H cmt to squeeze perfs. Tag TOC @ 10,096'.

7/2/13 SICP 700#, SITP 2700#. Cut csg @ 10,051'.

7/9/13 SICP 1750#. Try to establish rate thru cut @ 10,051', but couldn't get inj rate. Discussed w/ BLM. Decision made to run mech cutter to cut liner @ 10,000'.

7/11/13 SICP 1700#. Cut liner @ 10,000'. Jar on liner, could not get any movement.

7/13/13 SICP 1700#. RIH w/ 4-1/2" CICR & set @ 9,980'. SDFW.

7/16/13 SICP 2400#. Pump 25 sx class H cmt thru retainer @ 9,980' and out cut in liner @ 10,000'.

7/19/13 SICP 1500#. Tag cmt @ 9,860'. Drill out cmt down to CICR @ 9,980'. No break in cmt through perf hole @ 9,951'.

7/23/13 SICP 1400#. Discuss pressures w/ blm and they wanted to do a pressure up test on perf @ 9,951'. Pressure test at 700 psi for 30 mins, no leak off. BLM said we did not need to drill up CICR. Load 30' dump bailer and dump 30' class H cmt on top of CICR.

7/24/13 SICP 1400#. Tag TOC w/ wireline @ correlated depth of 9949'.

7/25/13 SICP 1400#. Talked to BLM & they wanted to see a tag of TOC w/ tubing. RIH to tag cmt w/ bit @ 9949'. BLM (Kent Caffall) witnessed tag.

7/29/13 MIRU. Install WH. Test to 3000# ok.

7/30/13 0 psi on csg & tbg. Release pkr & RBP. RIH w/ RBP & set @ 9600'. Set pkr & press test RBP to 3000# ok. Release prk & POOH. SWI.

08/01/13 Press test csg to 300 psi. RIH w/ pkr to 6502' – 100' below DV tool. Press up to 4000#. Held ok. Set pkr @ 6406'. Test csg to 4000#. Found leak @ 6504-6536'. RIH and latch on to RBP @ 9600'. SDFN.

Trinity 20 Fed 2 Recomplete to Wolfcamp 30015-34500

Page 2

08/02/13 POH w/ pkr & RBP. SDFN.

08/03/13 RIH w/ 7" composite plug and set @ 9592'. SWI. WO engineering evalution.

11/02/13 MIRU. Flowback well.

11/05/13 SICP 2000#. MIRU. POOH w/ tbg. SWI.

11/06/13 SICP 1300#. Finish POOH w/ tbg.

11/07/13 SICP 1350#. RU WL. RIH w/ 6" RGJB to tag composite plug @ 9592'. POH and RIH w/ 7" 10K composite plug & set 2" above previous plug. POOH. RD WL. SI.

11/08/13 SICP 300#. RIH w/ 7" pkr & set @ 6532'. Test csg & plug to 5800# for 30 mins. OK. Test csg above pkr to 5000# for 30 mins. OK. Pull pkr up hole to 6532'.

11/09/13 0# CSIP. MIRU cementers. Mix & pump 15 sx Class C cmt. Set pkr. WOC over weekend.

11/11/13 Release pkr & POOH. Tag cmt @ 6510'. RU swivel & stripper head, press test cmt pior to drill to 4000#. No leak off. Drill cmt from 6510' to 6532' cont to 6588'.

11/13/13 POOH w/ tbg. No obstructions. Ran shoe mill shoe past 6520'. POOH & LD. 11/14/13 Caliper log shows DV tool @ 6469', leak @ 6514. Set csg patch @ 6524-6464'. POOH.

11/15/13 POOH. Test csg & patch to 5800# for 30 mins. Ok. Charted. RIH w/ tbg.

11/21/13 Tag composite plug @ 9590'. DO. Tag 2nd plug @ 9592'. DO down to 9949' Circ sweep. Work bit thru liner top until clean. RD. SWI.

01/07/14 MIRU, SICP 1400#. RIH w/ WL tools to 9624', SWI.

01/08/14 could not get passed 9624'. SWI.

01/09/14 SICP 1200#. RIH & tag @ 9624'. Work thru debris to 9932'. Work thru from to to bottom w/ no restrictions. RD.

01/11/14 MIRU and perf Wolfcamp @ 9629-9930', 72 holes. WO frac.

04/03/14 MIRU frac trucks.

04/05/14 Perf @ 9164-9166'. Frac w/ 984826 gals total fluid, 860780# sand.

04/06/14 Flowback well.

04/10/14 DO composite plugs & CO to PBTD @ 9949'.

04/13/14 RIH & set pkr @ 9132'. POOH.

04/15/14 RIH w/ tbg & GL and set @ 9132'. GLV @ 1719, 3217, 4489, 5467, 6281, 6966, 7685, 8437, 9090'. Flowback well. Turn well over to production.