

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1300 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Smokey Bits State Com #5H	Facility Type	

Surface Owner	State	Mineral Owner		Lease No.	API#30-015-40070
---------------	-------	---------------	--	-----------	------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	36	18S	30E	330'	S	330'	W	Eddy County, NM

Latitude N 32.69781° Longitude W 103.93297°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	15 bbls oil, 95 bbls produced water	Volume Recovered	100 bbls
Source of Release	Frac tank bottom failure	Date and Hour of Occurrence	8/14/12	Date and Hour of Discovery	8/14/12
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD		
By Whom?	Christopher Jones	Date and Hour	8/14/12 @ 12:24 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

RECEIVED
APR 29 2013
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*




Describe Cause of Problem and Remedial Action Taken.*

Failure of a frac tank bottom caused 15 bbls of oil and 95 bbls of produced water to leak onto the ground. 100 bbls of produced water were recovered via vacuum truck.

Describe Area Affected and Cleanup Action Taken.*

Failure of a frac tank bottom caused 15 bbls of oil and 95 bbls of produced water to leak onto the ground. 90 bbls of produced water were recovered via vacuum truck. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 01/10/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones		Approved by District Supervisor: 	
Title: HES Specialist		Approval Date: 4/21/15	Expiration Date: N/A
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval: 	
Date: 4/25/13	Phone: (575) 397-8216	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2AP-1285