

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	McCall #2	Facility Type	Tank Battery

Surface Owner	Fee	Mineral Owner	Lease No. 30-015-29447
---------------	-----	---------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	24	18S	26E					Eddy

Latitude N 32.72665° Longitude W 104.34347°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	63 bbls	Volume Recovered	50 bbls
Source of Release	Transfer pump failure caused tank overflow	Date and Hour of Occurrence		Date and Hour of Discovery	07/01/2011 @ 8:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Kelton Beard-Oxy	Date and Hour	07/01/2011 @ 8:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

APR 29 2013

Describe Cause of Problem and Remedial Action Taken.*

NMOCD ARTESIA

Failure of a transfer pump caused 63 bbls of produced water to spill onto the ground. 50 bbls of produced water were recovered via vacuum truck and the pump was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 130' x 70'. Failure of a transfer pump caused 63 bbls of produced water to spill onto the ground. 50 bbls of produced water were recovered via vacuum truck and the pump was repaired. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher via email on 01/10/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Christopher Jones

Title: HES Specialist

E-mail Address: Christopher.Jones@oxy.com

Date:

4/25/13

Phone: (575) 397-8216

Approved by District Supervisor:

Approval Date: 4/21/15

Expiration Date: N/A

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

28P-822