

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: OXY USA INC	Contact: Dusty Wilson
Address: 4008 N. Grimes PMB #269, Hobbs, NM 88240	Telephone No.: 575-397-8247
Facility Name: Midwest L Federal #5	Facility Type: Oil well

Surface Owner: Federal	Mineral Owner: Federal	Lease No.: API #30-015-32364 2RP-625
------------------------	------------------------	---

LOCATION OF RELEASE

Unit Letter D	Section 34	Township 22S	Range 26 E	Feet from the 660	North/South Line FNL	Feet from the 330	East/West Line FWL	County Eddy
------------------	---------------	-----------------	---------------	----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude 32.354174 N Longitude -104.288548 W

NATURE OF RELEASE

Type of Release: Produced Water & Oil	Volume of Release: 60 bbls	Volume Recovered: 8 bbls
Source of Release: Poly Flow line	Date and Hour of Occurrence	Date and Hour of Discovery: 2/7/11 @ 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD left voice mail Terry Gregston - BLM	
By Whom? Kelton Beard - Oxy	Date and Hour: 2/7/11 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The flow line froze and ruptured. The well was shut-in, the flow line was repaired and well was returned to service.

Describe Area Affected and Cleanup Action Taken.\*

Talon/LPE was contracted for the correction of the release. The impacted area was excavated to a depth of 4-5 foot deep. Analytical testing was completed and the impacted soil was transported to Lea Land, LLC an approved disposal facility. The excavated area was backfilled to grade with new material transported from Lea Land, LLC. The backfill material was contoured to match the surrounding terrain and seeded with BLM mixture #3 and #4 (50/50 mix).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dusty Wilson	Approved by District Supervisor: 	
Title: OXY H.E.S. Specialist	Approval Date: 4/22/15	Expiration Date: N/A
E-mail Address: dusty_wilson@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 1/13/12	Phone: 575-397-8247	

\* Attach Additional Sheets If Necessary

2RP-625