Submit I Copy To Appropriate District Office	State of New Me	xico		Form C-103	
District 1 - (575) 393-6161	Energy, Minerals and Natur	ral Resources	WELL API NO.	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCERNATION DUMOION		30-015-36320		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION		5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE X		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	303	6. State Oil & G	as Lease No.	
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name o	r Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			LAKE MCMILLAN "21"		
1	Gas Well X Other		8. Well Number 002		
2. Name of Operator WESTERN RESERVES OIL CO	MPANY INC.		9. OGRID Numb	per	
3. Address of Operator			10. Pool name or Wildcat		
P.O. BOX 993, MIDLAND, TEXAS 79702			FOUR MILE DRAW; MORROW (GAS)		
4. Well Location					
Unit Letter; G;	1980 feet from the NORTH	line and 1980		EAST line	
Section 21	Township 19S 11. Elevation (Show whether DR,	Range 26E	NMPM	EDDY County	
	3,343' - (/ 13/14/ 13/14/ 		
12. Check	Appropriate Box to Indicate Na	ature of Notice,	Report or Other	Data	
NOTICE OF IN	ITENTION TO:	l cup	CECHENT DE	DODT OF	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WOR			SEQUENT RE ĸ □	ALTERING CASING	
the state of the s			LLING OPNS.	P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN					
DOWNHOLE COMMINGLE					
OTHER:		OTHER:			
	oleted operations. (Clearly state all p		d give pertinent dat	es, including estimated date	
	ork). SEE RULE 19.15.7.14 NMAC				
1) SET 5-1/2" CIBP @ 9,400	'; PUMP 25 SXS. CMT. @ 9,400'-9	210' CIRC WEL	I W/PYA FILIID		
	7,145'-6,975' (T/WC); WOC X TAG		Appro	red for plugging of well bore only.	
3) PUMP 25 SXS. CMT. @ 5	5,075'-4,925' (SPACER PLUG).		1350.36	ty under bond is retained pending receipt (3) (Subsequent Report of Well Plugging)	
4) PUMP 80 SXS. CMT. @ 3	PLUG. which	may be found at OCD Web Page under			
5) PUMP 40 SXS. CMT. @ 1,460'-1,207' (9-5/8"CSG.SHOE); WOC X TAG CMT. PLUG. 6) MIX X CIRC. TO SURF. 65 SXS. CMT. @ 478'-3' (13-3/8"CSG.SHOE).					
	ELLHEAD 3' B.G.L.; WELD ON S		CSGS. X INSTALI	L DRY HOLE MARKER.	
· .	·				
DURING THIS PROCEDURE WE TO THE REQUIRED DISPOSAL,	PLAN TO USE THE CLOSED-LO PER OCD RULE 19.15.17.	OP SYSTEM W/ A	STEEL TANK A	ND HAUL CONTENTS	
Spud Date:	Rig Release Da	ite:		NM OIL CONSERVATION	
				ARTESIA DISTRICT	
well must be player				MAY 1 1 2015	
I hereby certify that the information	above is true and complete to the be	est of my knowledg	e and belief.	MINI I I FOID	
SIGNATURE SIGNATURE	TITLE: AGE	NT	DA	RECEIVED TE: 05/06/15	
Type or print name: DAVID A. EY				ONE: 432.687.3033	
For State Use Only	1				
ADDROVED BY:	$\mathcal{M}_{\text{TITLE}}$	AL YOU	(B2)	TT 5/12/2015	
APPROVED BY: Conditions of Approval (if any):	A Table	The state of the s	DA DA	TE 5/12/2015	
× See AHac	hed COA'S				

OPERATOR WESTERN RESERVES OIL CO. INC. 30-015-36320 LEASENAME LAKE MCM THLAN "21" WELL # 002 26E SECT TWN 195 RNG 1980 WSL 1980 EW L **FROM** FORMATION @ TD MRRW TD: FORMATION @ PBTD PBTD: SIZE SET @ TOC TOC DETERMINED BY SURFACE 133/8 **ス** 子名 ' SURF CIRC. 95/8 INTMED 1 SURF. CIRC **INTMED 2** PROD 51/2 9775 SURF. CIRC SIZE TOC DETERMINED BY BOT TOP LINER 1 LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 9446 - 45231 PERFS INTMED 2 TOC PROD * REQUIRED PLUGS DISTRICT I PLUG RUSTLER (ANHYD) TYPE SACKS DEPTH PLUG **CMNT** YATES (297) JTS. OUEEN EXAMPLES 2-76" L-80 OН 25 SXS 9850' GRAYBURG PLUG#1 1257' 50 SXS SAN ANDRES PLUG#2 SHOE 8700'-8800' CIBP/35' 5300' CIBP 25 SXS CAPITAN REEF PLUG#3 5300' PLUG#4 **STUB** 50 SXS 4600'-4700' RETNR SQZ 200 SXS 400 DELAWARE PLUG#6 SURF 10 SXS 0-10' BELL CANYON PLUG#7 CHERRY CANYON PLUG#2 BRUSHY CANYON PLUG#3 BONE SPRING 3470 PLUG#4 2985 GLORIETA. PLUG#5 BLINEBRY PLUG#6 PLUG#7 TUBB PLUG#8 DRINKARD PLUG#9 ABO PLUG# 10 7060 WC PLUG# PENN PLUG# 8730 STRAWN 9020 ATOKA 9410 MORROW TD 9780 MOSS DEVONIAN 05/06/15.

PLUGGING & ABANDONMENT WORKSHEET

(3 STRING CSNG)

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG) 30-015-36320 OPERATOR WESTERN RESERVES OIL CO. INC. LEASENAME LAKE MCMILLAN "21" WELL 002 195 RNG SECT TWN 26E 1980 WS L 1980 EWL **FROM** CD20.65 sxs. FORMATION @ TD MERU TD: 9.780' @478'-3' FORMATION @ PBTD PBTD: SIZE SET @ TOC TOC DETERMINED BY 133/8" 133/8 SURFACE 3 18 ' SURF. CIRC. 95/8 INTMED 1 1410 CIRC SURF. INTMED 2 TOC SURF. 51/2 PROD 9775 SURF. CIRC. rh. TOP TOC DETERMINED BY SIZE BOT Pump 40 sxs. LINER 1 91460'-1207'-MB LINER 2 CUT & PULL @ TOP - BOTTOM INTMED 1 9446 · 9523' INTMED 2 OPENHOLE TOC PROD SURF * REOUIRED PLUGS DISTRICT I & Pump 80 sxs. @ PLUG **SACKS** TYPE DEPTH RUSTLER (ANHYD) X 3520'-2935'-TAG **CMNT PLUG** YATES EXAMPLES OH25 SXS PLUG# 1 9850' X Pump 255x5.@ 1257 PLUG#2 SHOE 50 SXS 8700'-8800' SAN ANDRES CIBP/35' PLUG#3 5300' X 5075'- 4925' PLUG#3 CIBP 25 SXS 5300' CAPITAN REEF X pump 25 sxs.@ **STUB** 50 SXS 4600'-4700' PLUG#4 7145'-6975'-MG RETNR SQZ 200 SXS 400 DELAWARE -PUMD 255X5.E 10 SXS **SURF** 0-10' BELL CANYON - crape 9400' CHERRY CANYON 9446- 9523 BRUSHY CANYON PI_183#2 3470 PLUG # 3 BONE SPRING PLUG# 4 2985 GLORIETA PLUG#5 PLUG#6 BLINEBRY PLUG#7 DRINKARD PLUG#8 PLUG#9 PLUG# 10 wc 7060 PLUG# PLUG# PENN 8730 STRAWN 9020 ATOKA 9410 MORROW TD 9780 . M38 DEVONIAN

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: (LESTEN EDEWED	
Well Name & Number: Sak M Millan 21 #	·Z
API#: 30.015-36320	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.
- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

AD 5/12/2015

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement,
 whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100 of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).