<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action OPERATOR Initial Report Final Report													
nAB!	15174	OPERA:	ГOR		M Initi	al Report		Final Repor					
Name of Co	ompany D	evon Energy				Contact D							
Address 64		Telephone No. 575.390.5850											
Facility Name Cooter 16 State Com 5H Facility Type Oil													
Surface Ow	vner State	r State API No. 30-015-37627											
LOCATION OF RELEASE													
Unit Letter D	Section 16	Township 25S	Range 29E	Feet from the 30		South Line FNL	Feet from the 1190	l	Vest Line WL	County Eddy			
Latitude: <u>32.110725</u> Longitude: <u>103.9877</u>													
NATURE OF RELEASE													
Type of Release Spill Mixture of produced water & oil							Volume of Release Volume Recovered 7 BBL						
Source of Release A fire tube gasket on heater treater blown out.							Date and Hour of Occurrence 6/16/15 at 10:35 am Date and Hour of Discovery 6/16/15 at 10:35 am					ry	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Jim Amos BLM Mike Bratcher OCD Pote and Hour						VSEDVA	
By Whom? Leonard Aguilar													
Was a Watercourse Reached?						6/17/15 at 10:00 am If YES, Volume Impacting the Watercourse							
was a water	COULSE NEA	11 1 E.S., VU	nume impacting	me wa	tercourse			2013					
If a Watercou	urse was In	npacted, Desc	ribe Full	v.*						RE	CEI	VED	
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.* On 6/16/15 at the Cooter 16-5 Battery at 10:35 am A fire tube gasket on heater treater blown out. Devon employee shut supply to the heater and opened the drain to the water tank, and shut in the cottontail 16-1.													
Describe Area Affected and Cleanup Action Taken.* Lease operator inspected the heater treater and found that the gasket around the fire tube (upper left corner) of the gasket approximately 10" long had blown out causing the release of oil and water. The spill was limited to about 8bbl total 4 BBL of oil and 4 BBL of produced water. 2 BBL was in lined containment and 2 BBL recovered, no holes in lined containment. 6 BBL was spilled on pad a 10 X 20 area and 5 BBL was recovered. An environmental company will be called out to evaluate area.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Signature, Tague atta Rayana						OIL CONSERVATION DIVISION							
Signature: Jeanette Barron													
Printed Name:	Jeanette B	Approved by Environmental Specialist:											
Title: Field Ad	lmin Suppo	A	Approval Date: 6/23/15 Expiration Date: N/A										
		 			1		, , ,	<u> </u>	spirationi L	anc.y VIII	<u></u>		
E-mail Address	s: Jeanette.	oarron@dvn	.com			onditions of <i>i</i> e mediatio s	• •	ules A	. Guidel	Attached nes			
Date: 6/19/15 Phone: 575.748.1813							Remediation per O.C.D. Rules & Guidelines						
Attach Additio	onal Sheets	s If Necessar	У		i.A	TER THA	N: 7[24]	5_		2	RF	-300L	