District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

> : * •

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 S. St. Fran	cis Dr., Santa	a Fe, NM 8750	;	Sa	nta F	e, NM 875	05					
Release Notification and Corrective Action												
NAB1523133089						OPERA	🖂 Initia	Initial Report 🔲 Final Report				
Name of Company: BOPCO, L.P. April 731					1	Contact: Amy Ruth						
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220						Telephone No. 575-887-7329						
Facility Name: Indian Flats Bass Federal SWD (SWD is located 2996 ft. SW of Well #1 ApI 30-015-24968)						Facility Type: Exploration and Production						
Surface Owner: Federal Mineral Owne						Federal			API No	. 30-015-2	4968	
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	_	South Line	Feet from the	East/V	Vest Line	County		
J	35	215	28E	1652	South		2150	East		Eddy		
Latitude32.433935° Longitude104.055036°												
NATURE OF RELEASE												
Type of Relea	ase Produ	ced Water			UNE		e of Release 145 bbls Volume Recovered 85 bb					
Source of Release 1/2" fitting on SWD pump							lour of Occurrenc					
							nknown time		8/8/2015	11:30 pm		
Was Immediate Notice Given?					quired	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)						
By Whom?	Tony Savoi	e			······	Date and H	our 8/9/2015 7	:33 am				
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. N/A						
16 - 11/-	T									VMAN		
If a Watercourse was Impacted, Describe Fully.*												
ARTESIA DIGENVATION												
AUG												
AUG 1 7 2015 Describe Cause of Problem and Remedial Action Taken.*												
Describe Cause of Problem and Remedial Action Taken.* A 1/2" inch fitting on the discharge side of the SWD pump failed. Pump shut down and fitting was repaired. RECEIVED												
KECEIVEN												
· 20												
Describe Area Affected and Cleanup Action Taken.*												
The leak affect	cted approx	imately 2,250	square ft.	area of caliche pa							ds from	the zero
perm containr	ment as wel	l as from the g	ground. T	he leak on the cal	iche is	within an area	previously lined	with 20	-mil plastic	•		
				· · · · · · · · · · · · · · · · · · ·								
				is true and compl								
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations, have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												an health
				ance of a C-141 r	eport d	loes not relieve	the operator of r	esponsi	bility for co	mpliance w	ith any	other
federal, state,	or løcal law	s and/or regu	ations					EDV	ATION	DIVISIO	NT	
XIIAA						OIL CONSERVATION DIVISION						
Signatyfe: Juny Cull												
Printed Name: Amy Ruth						Approved by Environmental Specialist: The Man						
\sim							SIG	≤ 1			A	
Title: Assistan			Approval Date: D/P 15 Expiration Date: N/H									
E-mail Address: ACRuth@basspet.com Conditions of Approval: Attached												
Date: 8/17/2015 Phone: 432-661-0571 Rediation per O.C.D. Rules & Guidelines												
Attach Additional Sheets If Necessary											MANK	
						SET ET PAINE.	<i></i>			2	-KP	JUVD