

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1523130328 **2100737** **OPERATOR** ☒ Initial Report ☐ Final Report

| | |
|--|---|
| Name of Company: BOPCO, L.P. | Contact: Bradley Blevins |
| Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 | Telephone No. 575-887-7329 |
| Facility Name: PLU 315H Flowline | Facility Type: Exploration and Production |

| | | |
|------------------------|----------------|--------------------|
| Surface Owner: Federal | Mineral Owner: | API No. 3001539166 |
|------------------------|----------------|--------------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| E | 13 | 24S | 30E | 1650 | | 710 | | Eddy |

Latitude: 32.20739 Longitude: 103.82718

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release: Crude Oil and Produced Water | Volume of Release: 10 oil, 52 barrels PW | Volume Recovered: None |
| Source of Release: Flowline | Date and Hour of Occurrence: 8-14-15 @ 12:00am | Date and Hour of Discovery: 8-14-15 @ 1:00am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos vis Email | |
| By Whom? Bradley Blevins | Date and Hour: 8-14-15 @ 3:48pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The PLU 315H flowline failed, an area night pumper discovered the release. Bopco EHS was notified Friday morning and was able to respond and collect information. It was discovered that 52 barrels of produced water and 10 barrels of oil was released to the ground surface. No fluid was recovered, the majority of the release remained within the caliche lease road.

Describe Area Affected and Cleanup Action Taken.*

The majority of the release remained within the caliche lease road, no fluid was recoverable at the time of discovery.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--------------------------------------|---------------------|--|------------------|
| Signature: <i>Bradley Blevins</i> | | OIL CONSERVATION DIVISION | |
| Printed Name: Bradley Blevins | | Approved by Environmental Specialist: <i>[Signature]</i> | |
| Title: Assistant Remediation Foreman | | Approval Date: | Expiration Date: |
| E-mail Address: bblevins@basspet.com | | Conditions of Approval: | |
| Date: 8-17-15 | Phone: 432-214-3704 | Remediation per O.C.D. Rules & Guidelines | |
| | | Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/21/15

2RP-3207