Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1 – (575) 393-6161	Energy, Minerals and Natural Resource	ces Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-015-30351
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISIO	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
DIFFERENT RESERVOIR. USE "APPLICA	TION FOR PERMIT" (FORM C. 1995) FOR SUCH	ROG Federal
1. Type of Well: Oil Well G	ias Well 🛛 Other	8. Well Number
	ias Well 🖾 Other 💢 🤰 2015	#1 9. OGRID Number
Name of Operator Shackelford Oil Company	YOU -	20595
3. Address of Operator	79701 RECEIVED	10. Pool name or Wildcat
203 W Wall St, Ste 200 Midland TX	79701 RECEIVE	Getty – Yates
4. Well Location		
Unit Letter P :	660' feet from the FSL line a	and 810' feet from the FEL line
Section 9		29E NMPM County Eddy
Section 7	11. Elevation (Show whether DR, RKB, RT, C	
TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comple of starting any proposed work proposed completion or record	MULTIPLE COMPL CASING/COMPL CASING/COMPL CASING/COMPL CASING/COMPLET CASING/COMPL	AL WORK ALTERING CASING CEMENT JOB Tails, and give pertinent dates, including estimated date ciple Completions: Attach wellbore diagram of
Changed out all bad 2 7/8 tubing (35 jts). Replaced with IPC 2 3/8" tubing. Set Packer at 1098' Circulated packer fluid.		NM OIL CONSERVATION ARTESIA DISTRICT
	ed by Richard Inge w/ OCD (Retained Chart)	
		RECEIVED
Spud Date:	Rig Release Date:	
<u> </u>		
I hereby certify that the information ab	bove is true and complete to the best of my kn	nowledge and belief.
310 VIII 20 0) _{TITLE} CFO	212 0/10/16
SIGNATURE TO THE SIGNATURE	TITLE CFO	DATEDATEDATE
Type or print name Brady Sho For State Use Only	1 10 1	
1 of State Ost Only	ackelford E-mail address: brady	
2/11\	ackelford E-mail address: brady	Shackelford PHONE (432) 6002.9795 Sbegiobal net DOW/JU DATE 9/3/15

State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary **David Catanach, Division Director**Oil Conservation Division



Date 8 11 115

API#30-015-30351

Dear Operator:

I have this date performed a Mechanical Integrity Test on the

If this test was successful the original chart has been retained by the NMOCD and will be scanned into the well's file in 7 to 10 days, pending receipt of the Form C-103 indicating the reason for this test. The well files are located at www.emnrd.state.nm.us/ocd/OCDOnline.htm

____ If this test was unsuccessful the original chart has been returned to the operator pending repair and retest of the well, which must be accomplished within 90 days. If this is a test of a repaired well, previously in non-compliance, all dates and requirements of the original non-compliance are still in effect. No expectation of extension should be construed as a result of this test.

___ If this test was for Temporary Abandonment include in your detailed description, on Form C-103, the location of the CIBP and any other tubular goods in the well, as well as your request for TA status. Include how long you are requesting the TA status for.

If this is a successful test of a repaired well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a <u>detailed</u> description of the repair to the well. Only after receipt of the C-103 will the non-compliance be closed.

____ If this is a successful Initial Test of an injection well you must submit a form C-103 to NMOCD within 30 days. This C-103 must include a <u>detailed</u> description of the work done on this well including the position of the packer, tubing information, the date of first injection, the tubing pressure and injection volume. Contact Karen Sharp at 575-748-1283 x109 to verify all required paperwork has been received before you can begin injection.

If I can be of additional service contact me at (575) 748-1283 ext 107.

Thank You,

Richard Inge Compliance Officer District II - Artesia

State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David MartinCabinet Secretary

David Catanach, DirectorOil Conservation Division

STREET NEW METON

Brett F. Woods, Ph.D. Deputy Cabinet Secretary

Response Required - Deadline Enclosed

Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"

23-Jul-15

SHACKELFORD OIL CO PO BOX 10665 MIDLAND TX 79702-

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

30-015-30351-00-00 ROG FEDERAL No.001 P-9-20S-29E Active Salt Water Disposal Well Test Date: Permitted Injection PSI: **Actual PSI:** 7/23/2015 Test Result: Repair Due: Test Reason: 5-year Test 10/26/2015 Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure **FAIL CAUSE:** Well would not pressure up. Tried to build up pressure and it would not build above 200psi. After shutting Comments on MIT: the pump off, there was an immediate drop in pressure on the casing back to zero.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.