

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**0AB1525734392**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Linn Operating Inc. <b>269324</b>		Contact E.L. Gonzales	
Address 2130 W Bender Blvd Hobbs, NM 88240		Telephone No. 575-738-1739	
Facility Name Russell Turner Injection Station (closest well Turner B #3)		Facility Type Water Station	
Surface Owner Federal		Mineral Owner	API No. closest well 30-015-05279

**LOCATION OF RELEASE**

Unit Letter D	Section 20	Township 17S	Range 31E	Feet from the 330	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.8263779 Longitude -103.8983841

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 25 bbls	Volume Recovered 0
Source of Release header line	Date and Hour of Occurrence 09/03/2015	Date and Hour of Discovery 09/03/2015 7:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**

**ARTESIA DISTRICT**

**SEP 09 2015**



**RECEIVED**

Describe Cause of Problem and Remedial Action Taken.\* Was looking for inj. leak, drove out Main header line found leak about 50 yards from road heading north from Water Station. Erosion- corrosion of line.

Describe Area Affected and Cleanup Action Taken.\* Produced water traveled aprox. 75 x 25yds southwest. Spill is estimated to be about 25bbls.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by Environmental Specialist: 	
Printed Name: E.L. Gonzales	Approval Date: 9/11/15	Expiration Date: N/A
Title: Production Supervisor	Conditions of Approval:	
E-mail Address: elgonzales@linenergy.com	Attached <input type="checkbox"/>	
Date: 09/09/2015	Phone: 505-504-8002	

\* Attach Additional Sheets If Necessary

REMEDIAL ACTION per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 10/14/15

2RP-3252