

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, New Mexico 87505

DISTRICT I

1625 N. Fench Dr., Hobbs, NM 88240

DISTRICT II

1301 W. Grand Ave., Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30-005-63563

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

ANDREW FEE

8. Well No.

1-Y

9. Pool Name or Wildcat

WILDCAT MORROW

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

GAS

WELL ☐

WELL ☒

OTHER

2. Name of Operator

ELK OIL COMPANY

3. Address of Operator

POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310

4. Well Location

Unit Letter

B

820

Feet From The

NORTH

Line and

1980

Feet From The

EAST

Line

Section

19

Township

10 SOUTH

Range

29 EAST

NMPM

CHAVES

County

10. Elevation (Show whether DF, RKE, RT, GR, etc.)

3892' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103

PLUG AND ABANDON WELL AS FOLLOWS:

05/23/03: PLUG #1 PUMP 30 SXS @ 8193'

PLUG #2 PUMP 30 SXS @ 6628'

PLUG #3 PUMP 50 SXS @ 5877'

PLUG #4 PUMP 30 SXS @ 3501'

PLUG #5 PUMP 65 SXS @ 3000' TAG 2784'

PLUG #6 PUMP 25 SXS @ 443'

PLUG #7 PUMP 10 SXS SURFACE PLUG

CIRCULATE 10# DRILLING MUD BETWEEN ALL PLUGS.

CUT OFF WELLHEAD, INSTALL DRY HOLE MARKER, RELEASE RIG AT 1:00 P.M. ON 05/25/03.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

PRESIDENT

DATE

6/6/03

TYPE OR PRINT

NAME

JOSEPH J. KELLY

TELEPHONE NO.

505-623-3190

(This space for State Use)

Field Supervisor

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

NOV 16 2005



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Lori Wrotenberg**

Director

**Oil Conservation Division**

*P/A OK To Release  
10/18/05  
[Signature]*

13 June 2003

Elk Oil Co.

P.O. Box 310

Roswell, New Mexico 88201

Form C-103 Report of Plugging for your Andrew Fee 1-Y B-19-10-29 API 30-005-63563

Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Name \_\_\_\_\_

  
\_\_\_\_\_  
Van Barton  
Field Rep. II

Title \_\_\_\_\_