Form 3160-5 (August 2007)	UNITED STATE DEPARTMENT OF THE	INTERIOR OCD Ar	tesia		FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010
BUREAU OF LAND MANAGEMENT			5. Lease Serial No. NMLC-054908		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
,	SUBMIT IN TRIPLICATE - Other	instructions on page 2.		7. If Unit of CA/Ag	reement, Name and/or No.
1. Type of Well	Gas Well Other			8. Well Name and N Fair 17 Federal #2	
2. Name of Operator Fair Oil, Ltd.	· · · · · · · · · · · · · · · · · · ·	• • •		9. API Well No. 30-015-41763	<u> </u>
3a. Address P.O. Box 689 Tyer TX 75710		3b. Phone No. (include area co 903-510-6527	ode)	10. Field and Pool of Cedar Lake (Glorid	• -
4. Location of Well (Footag 2310' FNL and 660' FWL, Sec 17,	e, Sec., T.,R.,M., or Survey Description, T175, R31E	)		11. Country or Paris Eddy	h, State
	12. CHECK THE APPROPRIATE BO	X(ES) TO INDICATE NATUR	E OF NOTIO	L CE, REPORT OR OT	HER DATA
TYPE OF SUBMISSI	ION	TY	PE OF ACT	ION	
Notice of Intent	Acidize	Deepen Fracture Treat		uction (Start/Resume) amation	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction	_	mplete porarily Abandon	Other
Final Abandonment No	otice Convert to Injection	Plug Back	U Wate	r Disposal	
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait	which the work will be performed or pro- f the involved operations. If the operative ted. Final Abandonment Notices must the is ready for final inspection.) Surface Casing approved 7-25-14 d to STC casing with DV tool. Pumper t on cement, run temperature survey Run 1*, tagged at 120', pumped 175	on results in a multiple completi- be filed only after all requiremen lue to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run	on or recomp ts, including en DV tool, 1" . tagged	letion in a new interva reclamation, have bee pumped additional at 160', pumped 50	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl ) sks Class C with 2% calcium
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait	the involved operations. If the operation ted. Final Abandonment Notices must the is ready for final inspection.) Surface Casing approved 7-25-14 d O STC casing with DV tool. Pumper t on cement, run temperature survey	on results in a multiple completi- be filed only after all requiremen lue to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run	on or recomp ts, including en DV tool, 1" . tagged	letion in a new interva reclamation, have bee pumped additional at 160', pumped 50	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl ) sks Class C with 2% calcium Copy Temperature log attach
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait	the involved operations. If the operation ted. Final Abandonment Notices must the is ready for final inspection.) Surface Casing approved 7-25-14 d O STC casing with DV tool. Pumper t on cement, run temperature survey	on results in a multiple completi- be filed only after all requiremen lue to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run	on or recomp ts, including en DV tool, 1" . tagged	letion in a new interva reclamation, have bee pumped additional at 160', pumped 50 6 bbls to surface. C	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl 9 sks Class C with 2% calciun Copy Temperature log attach SERVATION
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait	the involved operations. If the operation ted. Final Abandonment Notices must the is ready for final inspection.) Surface Casing approved 7-25-14 d O STC casing with DV tool. Pumper t on cement, run temperature survey	on results in a multiple completi- be filed only after all requiremen lue to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run	on or recomp its, including en DV tool, 1" . tagged	letion in a new interva reclamation, have bee pumped additional at 160', pumped 50 6 bbls to surface. C NM OIL CON	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl : ) sks Class C with 2% calcium Copy Temperature log attach <b>SERVATION</b> DISTRICT
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R	The involved operations. If the operation ted. Final Abandonment Notices must be is ready for final inspection.) Surface Casing approved 7-25-14 d 0 STC casing with DV tool. Pumper t on cement, run temperature survey Run 1*, tagged at 120', pumped 175	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium sks Class C with 2% calcium	on or recomp its, including en DV tool, 1", tagged , Circulated	letion in a new interva reclamation, have bee pumped additional at 160', pumped 50 6 bbls to surface. C NM OIL CON ARTESIA D	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl ) sks Class C with 2% calcium Copy Temperature log attach SERVATION DISTRICT 9 2015
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R	the involved operations. If the operation ted. Final Abandonment Notices must the is ready for final inspection.) Surface Casing approved 7-25-14 d O STC casing with DV tool. Pumper t on cement, run temperature survey	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium sks Class C with 2% calcium	on or recomp its, including hen DV tool, 1", tagged , Circulated	letion in a new intervareclamation, have been pumped additional at 160', pumped 50 6 bbls to surface. Constant of the second sec	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl 9 sks Class C with 2% calciun Copy Temperature log attach SERVATION DISTRICT 9 2015 IVED
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R	The involved operations. If the operation ted. Final Abandonment Notices must be is ready for final inspection.) Surface Casing approved 7-25-14 d 0 STC casing with DV tool. Pumper t on cement, run temperature survey Run 1*, tagged at 120', pumped 175	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium sks Class C with 2% calcium	on or recomp its, including hen DV tool, 1", tagged , Circulated	letion in a new intervareclamation, have been pumped additional at 160', pumped 50 6 bbls to surface. Constant of the second sec	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl ) sks Class C with 2% calcium Copy Temperature log attach SERVATION DISTRICT 9 2015
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R	the involved operations. If the operation ted. Final Abandonment Notices must be is ready for final inspection.) Surface Casing approved 7-25-14 do 0 STC casing with DV tool. Pumped to n cement, run temperature survey Run 1*, tagged at 120', pumped 175	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium sks Class C with 2% calcium NHICCD/OH (Typed) Title Production Date 12/16/20	on or recomp its, including en DV tool, 1", tagged , Circulated D/DO/JS ion Manager 014	letion in a new intervareclamation, have been pumped additional i at 160', pumped 50 6 bbls to surface. Compared to surface the surface of th	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl 9 sks Class C with 2% calciun Copy Temperature log attach SERVATION DISTRICT 9 2015 IVED
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R Hereby certify that the for Rodney K. Thomson Signature	the involved operations. If the operation ted. Final Abandonment Notices must be is ready for final inspection.) Surface Casing approved 7-25-14 do 0 STC casing with DV tool. Pumped to n cement, run temperature survey Run 1*, tagged at 120', pumped 175	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium Sks Class C with 2% calcium NiniOCD/OH (Typed) Title Producti	on or recomp its, including en DV tool, 1", tagged , Circulated D/DO/JS ion Manager 014	letion in a new intervareclamation, have been additional at 160', pumped 50 6 bbls to surface. Common ARTESIA E OCT 1 1 CE USE	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl : 0 sks Class C with 2% calcium Copy Temperature log attach SERVATION DISTRICT 9 2015 IVED PTED FOR RECOR
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R	the involved operations. If the operation ted. Final Abandonment Notices must be is ready for final inspection.) Surface Casing approved 7-25-14 do 0 STC casing with DV tool. Pumped to n cement, run temperature survey Run 1*, tagged at 120', pumped 175	on results in a multiple completion be filed only after all requirement lue to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium Sks Class C with 2% calcium NH: CCD/OH (Typed) Title Production Date 12/16/20 FOR FEDERAL OR ST	on or recomp its, including en DV tool, 1", tagged , Circulated D/DO/JS ion Manager 014	letion in a new intervareclamation, have been additional at 160', pumped 50 6 bbls to surface. Common artesia at 160', pumped 50 6 bbls to surface. Common artesia at 0 CT 1 1 CE USE	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl : 9 sks Class C with 2% calcium Copy Temperature log attach SERVATION DISTRICT 9 2015 IVED PTED FOR RECOR MAR 1,1,2015 U OF LAND MANAGEMENT RLSBAD FIELD OFFICE
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R (4. I hereby certify that the for Rodney K. Thomson Signature Approved by onditions of approval, if any, a	This Space is true and correct. Name (Printed THIS Space I) THIS Space I) THIS Space I) THIS Space I) THIS Space I) THIS Space I) This notice does equitable title to those rights in the subject	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium Sks Class C with 2% calcium Ni-1OCD/OH (Typed) Title Production Date 12/16/20 FOR FEDERAL OR ST	on or recomp its, including en DV tool, 1", tagged , Circulated D/DO/JS ion Manager 014	letion in a new intervareclamation, have been additional at 160', pumped 50 6 bbls to surface. Common artesia at 160', pumped 50 6 bbls to surface. Common artesia at 0 CT 1 1 CE USE	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl : 9 sks Class C with 2% calcium Copy Temperature log attach SERVATION DISTRICT 9 2015 IVED PTED FOR RECOR MAR 1,1, 2015
following completion of testing has been complet determined that the site i Follow up to cementing of Ran 12 jts 13 3/8, 48# H-4 bond with no returns. Wait returns. Wait on cement. R 4. I hereby certify that the for Rodney K. Thomson Signature Comproved by onditions of approval, if any, a nat the applicant holds legal or of thitle the applicant to conduct of ittle 18 U.S.C. Section 1001 an	This Space is true and correct. Name (Printed THIS Space I) THIS Space I) THIS Space I) THIS Space I) THIS Space I) THIS Space I) This notice does equitable title to those rights in the subject	on results in a multiple completion be filed only after all requirement due to lost circulation zone: d 550 sks with no returns, Op y, top of cement at 180'. Run sks Class C with 2% calcium Sks Class C with 2% calcium Title Production (Typed) Title Production Date 12/16/20 FOR FEDERAL OR ST not warrant or certify t lease which would Crime for any person knowingly at	on or recomp tis, including ten DV tool, 1", tagged , Circulated D/J-O/J ton Manager 014 ATE OFF	letion in a new intervareclamation, have been additional at 160', pumped 50 6 bbls to surface. Common artesia to surface and the surface and the surface additional at 160', pumped 50 6 bbls to surface. Common artesia to surface additional at 160', pumped 50 6 bbls to surface. Common and the surface additional at 160', pumped 50 6 bbls to surface. Common additional at 160 fbls to surface. Common additionad at 160 fbls to surface. Common additional at 160 fbls t	al, a Form 3160-4 must be filed en completed and the operator h 300 sks C+ Neat and 20 bbl 9 sks Class C with 2% calciun Copy Temperature log attach SERVATION DISTRICT 9 2015 IVED PTED FOR RECOR MAR 1,1, 2015 U OF LAND MANAGEMENT RLSBAD FIELD OFFICE Date