Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

**NMOCD** Artesia

FORM APPROVED = OMB NO. 1004-0135 Expires: July 31, 2010

## 5. Lease Serial No. NMNM0467930

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or C	CA/Agreement, Name	and/or No.	
I. Type of Well				8. Well Name and No. DALE H PARKE A TR 1 36			
Name of Operator Contact: DANIEL A JONES     PREMIER OIL & GAS INCORPORATED Mail: dan.jones@premieroilgas.com				9. API Well No. <b>39435</b> . 30-015-36 <del>92</del> 8-00-X1			
3a. Address	e No. (include area code) 2-470-0228		10. Field and Pool, or Exploratory LOCO HILLS				
ARTESIA, NM 88210	515-8327		II County or	r Parish, and State			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				·			
Sec 22 T17S R30E NENE 790FNL 420FEL 32.018562 N Lat, 103.438626 W Lon					EDDY COUNTY, NM		
12. СНЕСК АРРЕ	ROPRIATE BOX(ES) TO INDICA	TE NATURE OF N	OTICE, RE	EPORT, OR	OTHER DATA .		
TYPE OF SUBMISSION							
☐ Notice of Intent	☐ Acidize ☐ [	Deepen	☐ Product		ume) 🔲 Water	■ Water Shut-Off	
•	☐ Alter Casing ☐ I	Fracture Treat	☐ Reclamation		☐ Well I	■ Well Integrity	
Subsequent Report	Casing Repair	New Construction	☐ Recomplete		🛭 Other		
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	☐ Temporarily Abandon		workove	r Operations	
	☐ Convert to Injection ☐ F	Plug Back	□ Water D	isposal			
testing has been completed. Final Abdetermined that the site is ready for fit 10/14/2015?Drill out DV tool and DV tool and RiH to approx. ~6 10/15/2015?RU WSU and load down tubing.  10/16/2015?Install 10k compa frac valve to 4500 psi. RU lub with 2.75? HSC select fire gun perforate Yeso 1 5245-5640?	and drill out float shoe. RIH with bit a 300?  d hole with fresh water. Spot 1000 grain on flange, 10k frac valve and 10k pricator and wireline and run GR/CC as with Titan 22.7 gr charges (0.40?	all requirements, including and scraper, run scrapers and scrapers acides acide	aper across and POOH casing and te 4400?. RIH ion) and	, have been con laying est	NM OIL CON: ARTESIA D NOV 1 8	SERVATIO SERVATIO SISTRICT SOLUTION SERVATIO SISTRICT SOLUTION SERVATION SER	
14. I hereby certify that the foregoing is	Electronic Submission #322265 veri				NMOC	<del>)</del>	
Comm	For PREMIER OIL & GAS INCO hitted to AFMSS for processing by JE				(E)	1	
Name (Printed/Typed) DANIEL A	Title VICE PR	Title VICE PRESIDENT					
Signature (Electronic S	ubmission)	Date 11/02/20	1 ACCF	/ PTFD F0	B BECOPT		
	THIS SPACE FOR FEDE	RAL OR STATE O	FICEUS	E	V-9111	1	
pertify that the applicant holds legal or equivalent would entitle the applicant to condu- ritle 18 U.S.C. Section 1001 and Title 43 I	U.S.C. Section 1212, make it a crime for any	Office  y person knowingly and w	BUREA TA	NOV 1	ANAGEMENT MENT of agency of the	United	
States any false, fictitious or fraudulent s	tatements or representations as to any matte	r within its jurisdiction.		'	<u> </u>		

## Additional data for EC transaction #322265 that would not fit on the form

## 32. Additional remarks, continued

Yeso 1 5245-5640? (22) with 11,040 bbls slickwater carrying 168,157lbs of sand. Spot 1000 gal 15% HCL across Yeso 2 perfs. Shut-down. RU lubricator and wireline and RIH with 10K composite frac plug and 2.75? HSC select fire guns with Titan 22.7 gr charges (0.40? ehd, 20.5? penetration) and perforate Yeso 2 4651-4990? (22). Pump 3000 gal 15% HCl @ 16 bpm. Pumped 9,849 bbls slickwater carrying 157,495 lbs of sand. Spot 15% HCL 1000 gal across Yeso 3 perfs. Shut-down. RU lubricator and wireline and RIH with 10K composite frac plug and 2.75? HSC select fire guns with Titan 22.7 gr charges (0.40? ehd, 20.5? penetration) and perforate Yeso 3 4451-4594 (11). Shut down for the day. Frac Yeso in AM.

10/20/2015?Pump 3000 gal NE Fe 15% HCl @10 bpm. Pumped 6,223 bbls slickwater carrying 91,901 lbs of sand. Shut down.

10/21/2015?RIH w/ 4-3/4? bit to 3438? start foaming 30 min circulating. Tag sand @ 4582?. Wash to plug @ 4630? and drill 20 min. Hit next sand @ 5050? and wash to 5100?. Drill second plug and hit next sand @ 6185? and wash to 6285?. Circulate for 1 hr and pull out of hole w/ 21 jts. Rack stand back 172 jts in derrick.

10/22/2015?RIH w/ seating nipple, 38 jts 2-7/8? tubing, TAC, 2 jts of 2? marker subs, 132 jts total @ 5686. RIH w/ 2-1/2? x 2 x 20? Quinn frac pump, 80 3/4" rods, 80 7/8?, 65 1?, and 1:8?, 3:4?, 1:2? 1? subs. 26? polish rod. Load hole with 14 bbls of water and hang well on and begin pumping.