

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

JAN 08 2015  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1601139679 60137 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Rudy Zuniga Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-390-5435
Facility Name	Diamond PWU 22 #1H	Facility Type	Oil

Surface Owner	State	Mineral Owner	State	API No	30-015-38334
---------------	-------	---------------	-------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	22	19S	29E	575	North	330	West	Eddy

Latitude: N 32°65'19.52"

Longitude: W 104°07'01.29"

NATURE OF RELEASE

Type of Release Spill	Oil	Volume of Release	.5 bbl oil	Volume Recovered	.0 bbl
Source of Release	2 phase separator dump valve	Date and Hour of Occurrence	12.23.15 @ 11:30 am	Date and Hour of Discovery	12.23.15 @ 11:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson @ OCD		
By Whom?	Jesse Armendariz Assistant Production Foreman	Date and Hour	12.23.15 @ 11:40 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

2 phase separator dump valve was stuck causing a .5 bbl oil spray release. Well was shut in to prevent further release. The dump valve was rebuilt.

Describe Area Affected and Cleanup Action Taken.\*

.5 bbl oil spray was released on the East, South East side of the pad. None of the spray was recovered. The size of the affected area was 10'x20' off the pad. Environmental agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <i>Mike L...</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: 1/11/16 Expiration Date: N/A
E-mail Address: corina.moya@dm.com	Conditions of Approval:	
Date: 1.5.16 Phone: 575.746.5559	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 2/12/16	

\* Attach Additional Sheets If Necessary

2RP-3482