.Do not use th	UREAU OF LAND MANA NOTICES AND REPO is form for proposals to II. Use form 3160-3 (AP	RTS ON WELLS	SON WELLS		S. Lease Serial No. NMLC061581 G. If Indian, Allottee or Tribe Name	
	PLICATE - Other instruc		• <u>•</u> ••••••••••••••••••••••••••••••••••	7. If Unit or CA/Agree	ement, Name and/or No	
I. Type of Well				8, Well Name and No. FULLER 13 24 B2		
Oil Well Gas Well Oil Our Name of Operator MEWBOURNE OIL COMPAN	JACKIE LATHAN		9. API Well No. 30-015-43009-00-X1			
3a. Address		3b. Phone No. (include area code) Ph: 575-393-5905		10. Field and Pool, or Exploratory		
P O BOX 5270 HOBBS, NM 88241 4. Location of Well (Footage, Sec., T., R., M., or Survey Description				WILDCAT II. County or Parish, and State		
Sec 13 T26S R29E NWSW 26 32.041598 N Lat, 103.944007	520FSL 330FWL	•			•	
	ROPRIATE BOX(ES) TO	INDICATE NATURE	OF NOTICE R	FPORT OR OTHEI		
TYPE OF SUBMISSION			PE OF ACTION			
□ Notice of Intent		Deepen		ion (Start/Resume)	□ Water Shut-Off	
🛛 Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	• 🗖 Reclam		Well Integrity Sther	
Final Abandonment Notice	Change Plans	□ Plug and Abande □ Plug Back		arily Abandon	Drilling Operation	
determined that the site is ready for fi 12/03/2015 Spud 17 1/2" hole. 450 sks Class C w/additives. N 14.8#/g w/1.34 yd. Plug down to 3000# & Annular to 1500#. Drilled out with 12 1/4" bit.	. TD hole @ 757'. Ran 75 Mixed @ 13.5#/g w/1.74 y @ 3:45 A.M 12/04/15. Ci At 9:30 A.M. 12/05/2015,	r of 13.3/8" 54.5 J55 ST d. Tail w/200 sks Class rc 180 sks of cmt to the tested csg to 1500# for	&C csg. Cement C w/2% CaCl2. A Sit. WOC. Tested 30 min, held ok.	ed with lixed @ BOPE NM OIL CON ARTESIA		
Charts and schematic attached				JAN O	4 20160	
Bond on file: NM1693 nationw	IGE & NMB000919	NNIOCD	Is/Ive	RECE	IVED	
14. I hereby certify that the foregoing is	#Electronic Submission For MEWBOUF Nitted to AFMSS for proces	••	to the Carisbad/	(16JAS1384SE)		
Comm Name (Printed/Typed) JACKIE L/		Date 12	ACUEP 11 11/2015	D FUR RELL		
				E 1 2015 /	1 Minal	
Name (Printed/Typed) JACKIE L/		R FEDERAL OR STA	TE OFFICE H		THAN II (11/1717)	
Name (Printed/Typed) JACKIE L/			ha	MAN	Date	
Name (Printed/Typed) JACKIE LA	THIS SPACE FO	PR FEDERAL OR STA	BIRPAN	A LAND MANAGEMEN BBAD FIELD OFFICE		
Name (Printed/Typed) JACKIE LA	THIS SPACE FO	PR FEDERAL OR STA	BUREAU C CARLS			

	NAN WELDING SERVICES, INC.	
	MAL	
Comp	any <u>Mehibourne</u> Date <u>19-4-15</u> + <u>411er 19/24 B21M Fed. 1HCounty Editor</u>	
Lease	Fuller 13/24 B21M Fed. 1H County Eddy	
Drilli	ng Contractor Pattar son UTI 231 Plug & Drill Pipe Size 12"6-22 14" IF	
Accur	nulator Pressure: 3000 Manifold Pressure: 1500 Annular Pressure: 1000	
	Accumulator Function Test - 00&G0#2	
lo Ch	eck - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)	
•	Make sure all rams and annular are open and if applicable HCR is closed.	
۲	Ensure accumulator is pumped up to working pressure! (Shut off all pumps)	
	 Open HCR Valve. (If applicable) Close annular. 	
	3. Close all pipe rams.	
	4. Open one set of the pipe rams to simulate closing the blind ram.	
	5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).	
	6. Record remaining pressure 1700 psi. Test Fails if pressure is lower than required.	
0	a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system }	
	7. If annular is closed, open it at this time and close HCR.	
lo Ch	eck - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)	
Θ	Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:	
	a. {800 psi for a 1500 psi'system} b. {1100 psi for 2000 and 3000 psi system}	
	1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)	
	2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.	
	3. Record pressure drop <u>(000</u> psi. Test fails if pressure drops below minimum.	
0	Minimum: a. {700 psi for a 1500 psi system } b. {900 psi for a 2000 & 3000 psi system}	
`	eck - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)	
U UI		
•	Isolate the accumulator bottles or spherical from the pumps & manifold.	
ę	Open the bleed off value to the tank, (manifold psi should go to 0 psi) close bleed value.	
	1. Open the HCR valve, {if applicable}	
	2. Close annular	
tetu	3. With pumps only, time how long it takes to regain the required manifold pressure.	

. .

\$

. 1111-11.12 WELDING • BOP TESTING NIPPLE UP SERVICE - BOP LIFTS • TANDEM MUD AND GAS SEPARATORS Welding Seh Pg. Lovington, NM • 575-398-4540 -4-15 B64600 Company: MENBOUYNE Date: 13/24 Balm Fed. TH Drilling Contractor: Patterson 3 Z Plug Size & Type: Drill Pipe Size 3 M Required BOP: Installed BOP Appropriate Casing Valve Must Be Open During BOP Test * Check Valve Must Be Open/Disabled To Tost Kill Line Valve Dari her Valve #19 10000 82 Stand Pipe Valve Keily/ #24 #4 Annular #15 Top Drive Ō Ū =[[**M**= #22 #23 πw Pipe Rams #12 **IBOP** Valve -#3 #18 #17 Blind Rams #13 #89 Manual цф) (CO) Mud Gauge #1 IBOP Valve 16 Pump Valve Pump Valve _____ 250 #16 #20 #21 06 #8 ¢7 #11 #10 #1 #25 Pipe Rams #14 Super Choke Thart # Casing TEST # ITEMS TESTED TEST LENGTH HIGH PSI REMARKS LOW PSI 3000 OK 10 250 7 10 Flange. 10 Had to t. 2 56.10.13 ₹ OK 250 1500 hter 5 8 ۵K Putcheck Kalve 700) 5 200Bur 2 teri 0 Ŕ m Π Ø $2 \alpha U$ OA 9 a۲ 160 10 0 1 Man 2 Hoses no Tes \$





