

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB 23 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

## Release Notification and Corrective Action

**NAB1605654091** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <b>2160737</b>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 320H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 3001539810
------------------------	------------------------	--------------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	4	24S	30E	2590		1670		Eddy

Latitude: 32.24361 Longitude: 103.88657

## NATURE OF RELEASE

Type of Release: Crude oil and Produced water	Volume of Release: 11 barrels oil and 10 barrels PW	Volume Recovered: None
Source of Release: Flare Stack	Date and Hour of Occurrence: 2-19-16 @ 11:30am	Date and Hour of Discovery: 2-19-16 @ 11:55am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson and Jim Amos	
By Whom? Bradley Blevins	Date and Hour: 2-19-16 @ 12:32pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Fluid over ranged production vessels causing fluid to be released out the flare stack. An environmental response crew was dispatched to the location and began to scrape up the saturated soils; micro blaze was also applied to the vegetation.

Describe Area Affected and Cleanup Action Taken.\*

The fluid released affected the pasture to the north/northwest of the flare area. An environmental response crew was dispatched to the location and began to scrape up the saturated soils near the flare; micro blaze was also applied to the vegetation within the spray area. The area will be sampled and discussed with the NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Signed By <u>Mike Bratcher</u> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: <u>2/25/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	
Date: <u>2-23-16</u> Phone: 432-214-3704	Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 3/26/16

2RP-3563