

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

FEB 26 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1606057005 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation 873	Contact: Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name: EAU Emulsion Line (near the EAU M-141)	Facility Type: Emulsion Line
Surface Owner: Federal	Mineral Owner: API No. 30-15-22834

LOCATION OF RELEASE

Unit Letter C	Section 11	Township 18S	Range 27E	Feet from the 225'	North/South Line FNL	Feet from the 2280'	East/West Line FWL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	----------------

Latitude Longitude

NATURE OF RELEASE

Type of Release: produced water and oil	Volume of Release: 40 barrels of water 10 barrels of oil	Volume Recovered: 5 barrels of total fluid
Source of Release: Fiberglass line	Date and Hour of Occurrence: 2/24/2016	Date and Hour of Discovery: 2/24/2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker (BLM) Mike Bratcher (NMOCD)	
By Whom? Bruce Baker	Date and Hour: 2/25/2015 at 10:47 a.m. via email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A repair clamp on a buried 4 inch fiberglass line failed resulting in the loss of fluid. The line was isolated and a vacuum truck was dispatched to pick up standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The entire release was in the pasture. The area was mapped and a one call placed to permanently repair the line. Once the site is delineated a corrective action plan will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bruce Baker</u>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Environmental Technician	Approval Date: <u>2/29/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 2/26/2016	Phone: (432) 631-6982	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 3/31/16

2RP-3572