Form 3160-5 (April 2004)-

 a_t

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS


FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2003


		тариса, гланскі		
5	Lease S	erial No		
- 5	. Lease S	enal No).	

٥.	Louise Geriai Ivo.
	NMNM33437

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☐ ☐ Gas Well ☐ ☐ Other	PMS 8 Federal 8. Well Name and No.			
2. Name of Operator Matador Production Company	PMS 8 Federal #4			
3a. Address 3b. Phone No. (include area code)	9. API Well No. 30-015-26218			
PO BOX 1936 ~ ROSWELL NM 88202-1936 575.623.6601	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Shugart; Yates-7RS-QU-Grayburg			
1880' FSL & 1980' FEL, Sec. 8 SWNE, T18S, R31E	11. County or Parish, State Eddy, New Mexico			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R	REPORT, OR OTHER DATA			
TYPE OF SUBMISSION TYPE OF ACTION				
Acidize □ Deepen □ Production (St □ Alter Casing □ Fracture Treat □ Reclamation □ Casing Repair □ New Construction □ Recomplete □ Change Plans □ Plug and Abandon □ Temporarily A □ Convert to Injection □ Plug Back □ Water Disposal	Well Integrity Other bandon			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and tr Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Require following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclan determined that the site is ready for final inspection.) BLM Bond No. NMB0001079 SEE MIRU PU and POOH w/ production tbg, pump & rods	red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once			
RIH w/ workstring and squeeze perfs from 3,754 - 3,773' WOC, Pressure test casing to 500# Drill out cement MIRU WL and RIH and perf 1st Bone Spring Sand from 7300-7302', 7320-7322', 7330-7332' 7352 RIH w/ tubing and packer, set pkr @ ± 7,200' Acidize @ 7300-7302', 7320-7322', 7330-7332' 7352-7360', 7368-7376', 7425-7448' and 7558-7578' Swab test Frac @ 7300-7302', 7320-7322', 7330-7332' 7352-7360', 7368-7376', 7425-7448' and 7558-7578' POOH w/ pkr, RIH w/ production tbg, pump & rods. Put well on Production	NM OIL CONSERVATION ARTESIA DISTRICT FEB 2 2 2016			
14. Thereby certify that the foregoing is true and correct	RECEIVED/			
Name (Printed/Typed)	(DD)OVED			
Cury K. July	10/01/2015			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE 1 2 20/6				
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	ARLSBAD FIELD C. FICE			

(Instructions on page 2)





PMS 8 Federal 4 30-015-26218 Matador Production Company February 12, 2016 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by May 12, 2016.

- 1. Operator approved to squeeze as proposed.
- 2. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.
- 8. A minimum of a **3000** (**3M**) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done, C-102 form, and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 10. See attached for general requirements.

JAM 021216

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

