<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210	State of New Mexico Energy Minerals and Natural Resources		NM OIL CONSERVATIONForm C-141 ARTESIA DISTRICTRevised August 8, 2011			
<u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410	Oil Conservation Division 1220 South St. Francis Dr.			Subma MAR op to appropriate District Office in accordance with 19.15.29 NMAC.		
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	e, NM 87505					
Release Notification and Corrective Action						
NAB 1 408941057 OPERATOR Initial Report D'Final Repo						
Name of Company Oxy Permian Ltd.	16696		Casey Summers			
Address 6 Desta Drive, Midland, TX 7970	Telephone No. (575) 513-8289					
Facility Name Peaches 19 Federal CTB	Facility Type Battery					
Surface Owner BLM		API No. 30-015-40250				
LOCATION OF RELEASE						
Unit Letter Section Township Range	Feet from the North	h/South Line	Fect from the	East/West Line	County	
B 19 25S 27E					Eddy	
Latitude <u>N 32.12147°</u> Longitude <u>W 104.22839°</u>						
NATURE OF RELEASE Type of Release Oil and Produced water Volume of Release 7 bbls oil, Volume Recovered 7 bbls						hhle
	2 bbls proc	luced water				
Source of Release Heater gasket blew out	Date and F 03/03/2010	lour of Occurrenc	e Date and	Date and Hour of Discovery		
Was Immediate Notice Given? X Yes No Not Required If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM						BLM
By Whom? Kathy Purvis @ BBC Internationa	Date and Hour 03/04/2016 @ 3:29 pm If YES. Volume Impacting the Watercourse.					
Was a Watercourse Reached?	IT TES, volume impacting the watercourse.					
If a Watercourse was Impacted, Describe Fully.*						
Describe Cause of Problem and Remedial Action Taken.*						
A heater gasket blew out causing a spill of 7 bbls of oil and 2 bbls of produced water. A vacuum truck recovered 7 bbls of fluids and the gasket was replaced.						
Describe Area Affected and Cleanup Action Taken.*						
The affected area is approximately 150' x 60' with most of the leak staying inside the lined contaiment. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and						
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
			OIL CONSERVATION DIVISION			
Signature:	$11 / \lambda$					
Printed Name: Casey Summers	Approved by Environmental Specialist: The Management					
Title: NM Environmental Advisor		Approval Da	1e: 3 29 11	0 Expiration	Date: NIF	}
E-mail Address: Casey_Summers@oxy.com		Conditions o	f Annroval-			
20211	Remediation per O.C.D. Rules & Guidellached SUBMIT REMEDIATION PROPOSAL NO					
Date:)~28 - 1(_ Phone: * Attach Additional Sheets If Necessary	(575) 513-8289	LATER T		VIIIO		100 01 01
			<u></u>	~1114'	· 2	2RP. 3624