Submit One Copy To Appropriate District ONSERVATION Office NM OIL CONSERVATION State of New Mexico Office NM OIL CONSERVATION OFFI OFFI OFFI OFFI OFFI OFFI OFFI OFF	Form C-103
	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 MAR 3 1 2010	WELL API NO. 30-015-10300
OLI C. Clina Ca. Alamaia NINA 00010 ULL VALINOCAS VALIUNIN DI VIOLUNI	5. Indicate Type of Lease
District IV District IV Santa Fe, NM 87505	STATE FEE
District 17	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	HONDO SINGER C
PROPOSALS.) 1. Type of Well: ☐ Oil Well ☐ Gas Well ☒ Other	8. Well Number
2. Name of Operator	9. OGRID Number
OXY USA INC	16696
3. Address of Operator	10. Pool name or Wildcat
PO BOX 4294; HOUSTON, TX 77210	WC CISCO (GAS)
4. Well Location See Linit Letter E. 1989. feet from the NORTH line and 2310 feet from the WEST	2.15
Unit Letter F: 1980 feet from the NORTH line and 2310 feet from the WEST Section 18 Township 20S Range 27E NMPM County EDDY	_ime
11 Flevation (Show whether DR RKB RT CR etc.)	
3311'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB 🗌
OTHER:	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
<u>UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.</u>	
PERMANENTET STAMPED ON THE MARKER S SURFACE.	
☑ The location has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as possible to original ground contour and has been leveled as nearly as the location of the location o	been cleared of all junk, trash, flow lines and
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been remove	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and	Llines have been removed from lease and wel
location, except for utility's distribution infrastructure.	Thies have been removed from lease and wer
When all work has been completed, return this form to the appropriate District office to scho	-
Tan Z	2/20/1
SIGNATURE Frank Same TITLE HES OPS COORDI	NATORDATE
TYPE OR PRINT NAME _ FRANK BARNETT E-MAIL: <u>frank_barnett@oxy.com</u> _	
For State Use Only	
APPROVED BY: Conditions of Approval (if any):	$\mathbf{D}_{\mathbf{A}TF} \; \mathcal{U}_{-1} = \mathbf{A} \; \mathcal{L}$
Conditions of Approval (if any):	THE DATE OF

MAR 3 1 2016

RECEIVED

NMOCD,

As you can see below the Hondo Singer C-1 API number has been added to the P&A marker. Also a crew was on location for two days cleaning up trash and other debris that had been dumped on location.

I apologize for the inconvenience of sending the agency to a well that was not ready for closure. Please let us know if you have any questions.

Casey Summers 575-513-8289

Frank Burnett 575-921-6352

