

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

JUN 08 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616236118 243978 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: <b>Saber Oil &amp; Gas Ventures, LLC</b>	Contact: <b>JD Machacek</b>
Address: <b>400 W. Illinois, STE 950, Midland, TX 79701</b>	Telephone No.: <b>432-889-3928</b>
Well Name: <b>Yates Federal # 1</b>	Type: <b>Oil</b>

Surface Owner: <b>BLM</b>	Mineral Owner: <b>BLM</b>	API No.: <b>30-015-01035</b>
---------------------------	---------------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	7	20-S	27-E	330	N	990	E	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: <b>Leak</b>	Volume of Release: <b>N/A</b>	Volume Recovered: <b>0</b>
Source of Release: <b>Flowline</b>	Date and Hour of Occurrence: <b>N/A</b>	Date and Hour of Discovery: <b>N/A</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
**Flowline was punctured and then repaired.**

Describe Area Affected and Cleanup Action Taken.\*  
**Produced fluids collected off location in a low spot approximately 65' to the SW. Soil had noticeable TPH but no vegetation was affected or inhibited. Tentatively, Saber OGV plans to collect TPH contaminated soil and remediate it with the current Yates Federal Battery Remediation.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>JD Machacek</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>JD Machacek</u>		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: <u>Engineer</u>	Approval Date: <u>6/10/16</u>	Expiration Date: <u>N/A</u>	<input type="checkbox"/>
E-mail Address: <u>jd@saberogv.com</u>	Conditions of Approval:		Attached
Date: <u>6/2/16</u>	Phone: <u>432 685 0169</u>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

**SUBMIT REMEDIATION PROPOSAL NO**

**LATER THAN: 7/10/16**

**2RP-3729**

\* Attach Additional Sheets If Necessary

⊕ Confirmation Samples required  
from excavated area