

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 14 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1616738647

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	432-214-5175
Facility Name	Cotton Draw Unit #89	Facility Type	Salt Water Disposal

Surface Owner	Federal	Mineral Owner	Federal	API No	30-015-31381
---------------	---------	---------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	31E	250	South	1980	East	Eddy

Latitude: 32.1528893 Longitude: -103.7636414

NATURE OF RELEASE

Type of Release	Spill Oil	Volume of Release	10 BBLS	Volume Recovered	10 BBLS
Source of Release	Thief hatch	Date and Hour of Occurrence	6/13/2016 @ 10:40pm	Date and Hour of Discovery	6/13/2016 @ 10:40pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD-Mike Bratcher BLM-Jim Amos		
By Whom?	David Simmons, Assistant Production Foreman	Date and Hour	OCD- 6/13/2016 @ 4:19am BLM- 6/13/2016 @ 4:21am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

The water hauler connected and unloaded produced water into the basic sediment and water line which was only open to the oil tank resulting in a release of 10 BBLS of oil from the thief hatch. The driver shut down and disconnected from the line to prevent further release.

Describe Area Affected and Cleanup Action Taken.*

10 BBLS of oil was released from the thief hatch on the oil tank. All 10 BBLS oil released remained in lined containment. None of the released oil left location. Vacuum truck recovered approximately all 10 BBLS of the released oil. The liner was checked for hole, no holes were found in the liner. No further actions is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Signed By: <u>Mike Bratcher</u>	
Title: Field Admin Support	Approved by Environmental Specialist:	Approval Date: 6/14/16 Expiration Date: N/A
E-mail Address: Sarah.Gallegos-Troublefield@dv.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 6/13/2016 Phone: 575.748.1864		

* Attach Additional Sheets If Necessary

220-3142