	ch Dr., Hobbs, id Avenue, Ar	esia, NM 8821	0				al Resource	5			evised Octo	
District III 1000 Rio Braz	os Road, Azte	e. NM 87410				ervation Di					Office in	accord
<u>District IV</u> 1220 S. St. Fra	ancis Dr., San	a Fe, NM 8750	5			th St. Franc Fe, NM 87:				w	ith Rule 1	16 on ide of
			Re	ease Notifi				Actio	n			
					e	OPERA				ial Report	🖾 F	inal R
Name of C		COG Opera			.2	Contact	Pat Ell				<u> </u>	
Address Facility Na		xas, Suite 10 George State	,	and, TX 79701 attery		Telephone Facility Typ		0-0077 Battery				
Surface Ov				Mineral	<u></u>			Jattery	Tanna			9694(
Surface Ov	when Stat	.c								No. <del>(API#)</del> ) -0(5 ·		
Unit Letter	Section	Township	Range	Feet from the		N OF RE	LEASE Feet from th	e East/	West Line	County	001	- 1
J	12	17\$	28E			• • • • • • • • • • • • • • • • • • • •					nu NM	(
	12		<u> </u>	I	_L	<b>F</b>	I			Eddy Cour	niy, awi	
			1	Latitude <u>N 32</u>			ide <u>W 104 07</u>	<u>.000</u>				
Type of Rele	use Produ	lood water		NAT	URE	Volume of		bls	Volume	Recovered	7 bbls	
Source of Re			harge sid	e of water pump		Date and H	lour of Occurre		Date and	Hour of Disc	covery	
Was Immedi	ate Notice C	iven?				03/12/2012 If YES, To			03/12/201	12@ 6:30 a.n	<u>n.</u>	
			Yes 🛛	No 🖾 Not R	equired							
By Whom?						Date and H						
Was a Water	course Reac		Yes 🛛	No		If YES, Vo	olume Impactin	g the Wate	ercourse.			
						If YES, Vo	olume Impactin	g the Wate	ercourse.			•
Was a Water If a Watercou Describe Cau	urse was (mp	macted, Descrit	be Fully.* ial Action	i Taken.*	to vibra					ed.		•
Was a Watern If a Watercou Describe Cau	urse was Imp use of Proble e on the disc	macted, Descrit mand Remed harge side of	be Fully.* ial Action the water	) Taken.* pump failed due	to vibra					ed.		•
Was a Water If a Watercou Describe Cau The '/' nipple Describe Area Initially 8 bbls roughly 10' x were picked u	urse was Imp use of Proble e on the disc a Affected an s of produce 60' inside the p and the ov roved remed	mand Remed harge side of d Cleanup Ad d water were the tank battery erspray area	be Fully.* ial Action the water ction Take released f y with an a was scrape	) Taken.* pump failed due	mp and measur	tion and corros we were able t ing roughly 30 pill area was in	sion. The ¼" r to recover. 7 bb D' x 50' on loca dentical to the	ipple has Is with a vition outsispilt from	been replac	k. The spill nk battery. A	All free lic CD agree	juids d to
Was a Water If a Watercou Describe Cau The 'A'' nipple Describe Area Initially 8 bbls roughly 10' x were picked u allow the appr site backfilled. hereby certify egulations all public health of hould their op	urse was Imp ise of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the inn operators ar or the enviro perations hav ment. In add	m and Remed harge side of nd Cleanup Ad d water were i the tank battery erspray area v iation plan for formation give e required to noment. The a re failed to addition, NMOC	be Fully.* ial Action the water ction Take released f y with an a was scrape r the spill en above i report and cceptance equately i D accepta	Taken.* pump failed due en.* rom the water put area of overspray ed with a backhoo	mp and measures. The shandle cre to the lease not t by the mediate	tion and corros we were able t ing roughly 30 pill area was is this spill as we best of my k stifications and NMOCD mar contamination	sion. The '4'' i to recover. 7 bb 0' x 50' on loca dentical to the ell. The impact mowledge and i perform corre rked as "Final n that pose a th	ipple has ls with a v tion outsi spill from ed soil wa understan- ctive actio Report" da reat to gro	been replac /acuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bound water,	k. The spill nk battery. A . The NMO a clay liner i ant to NMO ases which m ve the operat surface wate	All free lic CD agree installed, CD rules a ay endang tor of liab er, human	uids d to and the and ger ility health
Was a Water If a Watercou Describe Cau The 'A'' nipple Describe Area Initially 8 bbls were picked u allow the appr site backfilled. hereby certiff egulations all ublic health o hould their op r the environ	urse was Imp ise of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the inn operators ar or the enviro perations hav ment. In add	m and Remed harge side of nd Cleanup Ad d water were i the tank battery erspray area v iation plan for formation give e required to noment. The a re failed to addition, NMOC	be Fully.* ial Action the water ction Take released f y with an a was scrape r the spill en above i report and cceptance equately i D accepta	Taken.* pump failed due en.* irom the water put area of overspray ed with a backhoc of 07/27/2011 to is true and comple for file certain re of a C-141 repor nvestigate and re	mp and measures. The shandle cre to the lease not t by the mediate	tion and corros we were able t ing roughly 30 pill area was is this spill as we best of my k stifications and NMOCD mar contamination	sion. The '4'' i to recover. 7 bb 0' x 50' on loca dentical to the ell. The impact mowledge and i perform corre rked as "Final n that pose a th	ipple has ls with a vition outsi- spill from ed soil wa understand ctive actio Report" do reat to gro responsib SERVA	been replac vacuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bund water, ility for cor ATION I	k. The spill nk battery. A . The NMO a clay liner i ant to NMO ases which m ve the operat surface wate npliance with DIVISION	All free lic CD agree installed, CD rules a aay endang tor of liab r, human h any othe	uids d to and the and ger ility health gr
Was a Water If a Watercou Describe Cau The 'A'' nipple Describe Area Initially 8 bbls were picked u allow the appr site backfilled. hereby certiff egulations all ublic health o hould their op r the environ	urse was Imp ise of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the inn operators ar or the enviro perations hav ment. In add	m and Remed harge side of nd Cleanup Ad d water were to the tank battery erspray area w iation plan for formation give e required to noment. The a re failed to addition, NMOC	be Fully.* ial Action the water ction Take released f y with an a was scrape r the spill en above i report and cceptance equately i D accepta	Taken.* pump failed due en.* irom the water put area of overspray ed with a backhoc of 07/27/2011 to is true and comple for file certain re of a C-141 repor nvestigate and re	mp and measures. The shandle cre to the lease not t by the mediate	tion and corros we were able 6 ing roughly 30 pill area was is this spill as we be best of my k prifications and NMOCD mar contamination we not relieve	sion. The '4'' i to recover 7 bb 0' x 50' on loca dentical to the ell. The impact in owledge and i perform corre rked as "Final i n that pose a th the operator of <u>OIL CON</u>	ipple has ls with a v tion outsi spill from ed soil wa understand ctive actio Report* do reat to gro responsib SERVA	been replac vacuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bund water, ility for cor ATION I	k. The spill nk battery. A . The NMO a clay liner i ant to NMO ases which m ve the operat surface wate npliance with DIVISION	All free lic CD agree installed, CD rules a ay endang tor of liab er, human h any othe	uids d to and the and ger ility health gr
Was a Water If a Watercou Describe Cau The '/' nipple Describe Area Initially 8 bbls roughly 10' x were picked u allow the appr site backfilled. hereby certiff egulations all bublic health o hould their op r the environ cederal, state, o	urse was Imp ase of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the imp operators ar or the enviro perations have ment. In add or local laws	m and Remed harge side of the nd Cleanup Ad d water were the tank battery erspray area v iation plan for formation give e required to the ment. The a- re failed to ad- lition, NMOC and/or regula	be Fully.* ial Action the water ction Take released f y with an a was scrape r the spill en above i report and cceptance equately i D accepta	Taken.* pump failed due en.* irom the water put area of overspray ed with a backhoc of 07/27/2011 to is true and comple for file certain re of a C-141 repor nvestigate and re	mp and measures. The shandle cre to the lease not t by the mediate	tion and corros we were able 6 ing roughly 30 pill area was is this spill as we be best of my k prifications and NMOCD mar contamination we not relieve	sion. The '4'' i to recover. 7 bb 0' x 50' on loca dentical to the ell. The impact mowledge and i perform corre rked as "Final i n that pose a th the operator of	ipple has ls with a v tion outsi spill from ed soil wa understand ctive actio Report* do reat to gro responsib SERVA	been replac vacuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bund water, ility for cor	k. The spill nk battery. A . The NMO a clay liner i ant to NMO ases which m ve the operat surface wate npliance with DIVISION	All free lic CD agree installed, CD rules a aay endang tor of liab r, human h any othe	uids d to and the and ger ility health gr
Was a Water If a Watercou Describe Cau The 'A'' nipple Describe Area Initially 8 bbls roughly 10' x were picked u allow the appr site backfilled. hereby certific egulations all bublic health of hould their op r the environic cderal, state, co ignature: rinted Name:	urse was Imp ase of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the imp operators ar or the enviro perations have ment. In add or local laws	m and Remed harge side of the nd Cleanup Ad d water were the tank battery erspray area v iation plan for formation give e required to the ment. The a- re failed to ad- lition, NMOC and/or regula	be Fully.* ial Action the water ction Take released f y with an a was scrape r the spill en above i report and cceptance equately i D accepta	Taken.* pump failed due en.* irom the water put area of overspray ed with a backhoc of 07/27/2011 to is true and comple for file certain re of a C-141 repor nvestigate and re	mp and measurers. The shandle cre to the lease not t by the mediate cport do	tion and corros we were able 6 ing roughly 30 pill area was is this spill as we be best of my k prifications and NMOCD mar contamination we not relieve	sion. The '4'' i to recover 7 bb 0' x 50' on loca dentical to the ell. The impact inowledge and i perform corre rked as "Final i n that pose a th the operator of <u>OIL CON</u> istrict Supervis	ipple has ls with a v tion outsi spill from ed soil wa understand ctive actio Report* do responsib SERVA or:	been replac vacuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bund water, ility for cor ATION I	k. The spill nk battery. A 1. The NMO a clay liner i ant to NMO ases which m ve the operat surface wate npliance with DIVISION	All free lic CD agree installed, CD rules a aay endang tor of liab r, human h any othe	uids d to and the and ger ility health gr
Was a Water If a Watercou Describe Cau The 'A'' nipple Describe Area Initially 8 bbls roughly 10' x were picked u allow the appr site backfilled. hereby certific egulations all bublic health of hould their op r the environic cderal, state, co ignature: rinted Name:	urse was Imp ise of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the info operators ar or the enviro perations hav ment. In add or local laws	m and Remed harge side of the nd Cleanup Ad d water were the tank battery erspray area v iation plan for formation give e required to the ment. The a- re failed to ad- lition, NMOC and/or regula	be Fully.* ial Action the water ction Take released f y with an a was scrape r the spill en above i report and cceptance equately i D accepta	Taken.* pump failed due en.* irom the water put area of overspray ed with a backhoc of 07/27/2011 to is true and comple for file certain re of a C-141 repor nvestigate and re	mp and measures. The shandle cre to the lease not t by the mediate eport do	tion and corros we were able t ing roughly 30 pill area was ic this spill as we be best of my k orifications and NMOCD mar contamination we not relieve	sion. The '4" r to recover 7 bb 0' x 50' on loca dentical to the ell. The impact inowledge and d perform corre- rked as "Final i n that pose a th the operator of <u>OIL CON</u> istrict Supervis	ipple has ls with a v tion outsi spill from ed soil wa understand ctive actio Report* do responsib SERVA or:	been replace vacuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bund water, oility for cor ATION I	k. The spill nk battery. A . The NMO a clay liner i ant to NMO ases which m ve the operat surface wate npliance with DIVISION	All free lic CD agree installed, CD rules is aay endan; tor of liab er, human h any othe	uids d to and the and ger ility health gr
Was a Water If a Watercou Describe Cau The 'A'' nipple Describe Area Initially 8 bbls roughly 10' x were picked u allow the appr site backfilled. hereby certific egulations all bublic health of hould their op r the environic cderal, state, co ignature: rinted Name: itle: HSE Co- mail Address	urse was Imp ise of Proble e on the disc a Affected an s of produce 60' inside th op and the ov roved remed by that the info operators ar or the enviro perations hav ment. In add or local laws	m and Remed harge side of the nd Cleanup Ad d water were the etank battery erspray area w iation plan for formation give e required to the mment. The a- tre failed to add lition, NMOC and/or regula	be Fully.* ial Action the water ction Take released f y with an a was scraper r the spill en above i report and cceptance equately i D accepta tions.	Taken.* pump failed due en.* irom the water put area of overspray ed with a backhoc of 07/27/2011 to is true and comple for file certain re of a C-141 repor nvestigate and re	mp and ineasures. The shandle ere to the lease not t by the mediate eport do	tion and corros we were able to ing roughly 30 pill area was in this spill as we best of my k wifications and NMOCD mar contamination wes not relieve hyproved by D pproval Date: onditions of A	sion. The '4" r to recover 7 bb 0' x 50' on loca dentical to the ell. The impact inowledge and d perform corre- rked as "Final i n that pose a th the operator of <u>OIL CON</u> istrict Supervis	ipple has ls with a v tion outsi spill from ed soil wa understand ctive actio Report* do responsib SERVA or:	been replace vacuum truc de of the tai 07/27:2011 is removed, d that pursu ons for relea bes not relie bund water, oility for cor ATION I	k. The spill nk battery. A 1. The NMO a clay liner i ant to NMO ases which m ve the operat surface wate npliance with DIVISION	All free lic CD agree installed, CD rules is aay endan; tor of liab er, human h any othe	uids d to and the and ger ility health gr

ないのないとない

間外における

日本に見て