

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
Form C-141
Revised August 8, 2011

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 22 2016
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAME <u>0AB1617548017</u>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Yates Petroleum Corporation		Contact Robert Asher		
Address 104 S. 4 th Street		Telephone No. 575-748-1471		
Facility Name Polo AOP Federal Com. #2		Facility Type Battery		
Surface Owner Fee		Mineral Owner Federal	API No. 30-015-20334	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	10	19S	25E	1980	South	1980	East	Eddy

Latitude 32.67346 Longitude 104.46982

NATURE OF RELEASE

Type of Release Oil	Volume of Release 0.5 B/O	Volume Recovered 0 B/O
Source of Release Flare	Date and Hour of Occurrence 6/14/2016; AM	Date and Hour of Discovery 6/14/2016; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Separator oil dump became plugged, pushing oil into flair line, causing the release and igniting an area of fee surface pasture on fire. Fire Department and crews were called.

Describe Area Affected and Cleanup Action Taken.*

The approximate pasture area of 50' x 300' north of the battery/location was burned. Any necessary equipment was repaired. Per the surface owner (Wilbanks Land & Cattle) the burn area is to be left as is and allowed to re-vegetate naturally. Depth to Ground Water: >100'; Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on that the released 0.5 B/O was consumed in the fire, the fire did not involve any other YPC production equipment and the surface owner has requested no further actions on the pasture, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Robert Asher		Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor		Approval Date: <u>6/23/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com		Conditions of Approval: <u>FINAL</u>	
Date: June 21, 2016 Phone: 575-748-4217		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-5152