

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 01 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. **240737** Contact: Amy Ruth

Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329

Facility Name: JRU #55 Battery Facility Type: Exploration and Production

Surface Owner: Federal Mineral Owner: Federal API No. 30-015-27589

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| F | 17 | 23S | 31E | 2060 | North | 1850 | West | Eddy |

Latitude 32.306040° Longitude -103.802369°

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-------------------------|----------------------------|------------------------|
| Type of Release | Produced Water and Crude Oil | Volume of Release | 7 bbls PW 3 bbls oil | Volume Recovered | 2 bbls PW 1 bbl oil |
| Source of Release | Oil circulating line | Date and Hour of Occurrence | 6/22/2016 time unknown | Date and Hour of Discovery | 6/22/2016 1 pm |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | N/A | | |
| By Whom? | N/A | Date and Hour | N/A | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | N/A | | |

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

Leak occurred on the oil circulating steel line in the portion buried in the tank earthen berm. Leak was due to a hole developing in the line due to external corrosion. Line was clamped until section can be repaired.

Describe Area Affected and Cleanup Action Taken.*

Leak affected 347 ft² of caliche within the tank earthen berm. Standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|----------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: Amy C. Ruth | Approved by Environmental Specialist:  | |
| Title: EHS Remediation Specialist | Approval Date: 7/1/16 | Expiration Date: N/A |
| E-mail Address: ACRuth@basspet.com | Conditions of Approval: Remediation per O.C.D. Rules & Guidelines | |
| Date: 7/1/2016 Phone: 432-661-0571 | SUBMIT REMEDIATION PROPOSAL NO | |

* Attach Additional Sheets If Necessary

LATER THAN: 8/7/16

2RP-3761