

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 22 2016
RECEIVED
Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1621049514

Name of Company WPX Energy Inc/RKI <i>244289</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 5315 Buena Vista Dr.		Contact Karolina Blaney	
Facility Name: RDX Federal 21-21		Telephone No. 970 589 0743	
		Facility Type: Well Pad	
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-41267

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	21	26S	30E	1650	FNL	990	FWL	Eddy

Latitude: 32.030564 N Longitude: -103.8912511 W

NATURE OF RELEASE

Type of Release: Produced Water and Oil	Volume of Release: 15 Bbls	Volume Recovered: 5 Bbls
Source of Release Pipeline valve located in a valve can	Date and Hour of Occurrence 7/8/2016	Date and Hour of Discovery 7/8/2016 - 1020 hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 7/8/16- 13:50 hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

This spill was caused by the stuffing box failure. Approximately 13 bbls of produced water and 2 bbls of oil were spilled on location. 5 bbls of the spilled material were recovered with a vacuum truck. The impacted soil was scraped and hauled off for disposal.

Describe Area Affected and Cleanup Action Taken.*

The impacted area will be sampled for BTEX and TPH in accordance with NM OCD Guidelines for Remediation of Leaks, Spills, and Releases. Further remediation will be based on these results. The total ranking score for this site is 10 and the site will be remediated to levels specified in 10-19 column of the Guidelines document. This spill did not leave the well pad location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Karolina Blaney</i>	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: <i>7/25/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Karolina.blaney@wpenergy.com	Conditions of Approval:	
Date: 7/22/2016 Phone: 970-589-0743	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>9/1/16</i>	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

LATER THAN: *9/1/16*

2RP-3801